

# SURVEY & REMONUMENTATION

FEB 26 2001

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

<u>LIVINGSTON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	<u>T 3 N R 3 E</u>	<u>C-04</u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
	T <u>    </u> R <u>    </u>	<u>    </u>
2. Property Controlling in Section	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
3. Miscellaneous Property in Sec.	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>
	S <u>    </u> T <u>    </u> R <u>    </u>	<u>    </u>

2000 OCT 30 A 9:22

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

LSC #1336m

Register of Deeds Stamp & File Number

4. Lot No.         , Recorded Plat           
5. Private Claims         

I, JACK K. SMITH, in a field survey on OCTOBER 11, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7	●	3		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SYLVESTER SIBLEY SET POST  
MAPLE 8" S17 1/2°W 3.3'  
IRONWOOD 8" N44°E 21.78'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE EXISTING CORNER IS A 3/4" ID PIPE APPROXIMATELY 3' EAST OF THE CENTERLINE OF STOW ROAD (GRAVEL). THERE IS A FENCE LINE AND TREE ROW TO THE EAST AND A CONCRETE MONUMENT AND MOWED YARD DIVISION LINE TO THE WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-04 WEST 1/4 CORNER SECTION 8, T3N, R3E, HANDY TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  
SET 1 1/4" x 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED SURVEYOR #35999 IN PLACE OF THE 3/4" PIPE THAT CURRENTLY MARKS THE CORNER.

EAST	SPIKE AND LIV. CO. REMON TAG IN NORTH SIDE OF UTILITY POLE	16.65'
S20°E	SPIKE AND LIV. CO. REMON TAG IN WEST SIDE OF 36" MAPLE	51.23'
S30°W	SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF 34" HICKORY	66.90'
WEST	SPIKE AND LIV. CO. REMON TAG IN NORTH SIDE OF 13" PINE	29.24'
WEST	CONCRETE MONUMENT FOR SLANKER'S SUBDIVISION	32.74'
WEST	3' +/- CENTER LINE OF STOW ROAD	

Signed by

Date 10-16-2000

Surveyor's Michigan License No. 35999



P.A. 345 1980, APPROVED BY LIVINGSTON COUNTY

PEER GROUP ON 4-19-2000, CO. REP JED

APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995