

SURVEY &  
REMONUMENTATION

FEB 26 2001

FILED

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

2000 OCT 30 A 9:22

LIVINGSTON  
(County)  
1. Public Land Survey Located In: Corner Code #  
T 3 N R 3 E E-03  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48843

a LSC #1340m

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, JACK K. SMITH, in a field survey on OCTOBER 11, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SYLVESTER SIBLEY SET POST  
WHITE OAK 26" N60°W 34.32'  
WHITE OAK 8" S17 1/2°E 17.16'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE EXISTING CORNER IS A 1/2" REROD 2 FEET WEST OF THE CENTER LINE OF NICHOLSON ROAD (PAVED). THERE IS LIGHT OCCUPATION TO THE EAST AND A TREE ROW AND A FENCE LINE TO THE WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-03 NORTHEAST CORNER SECTION 8, T3N, R3E, HANDY TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  
SET 1 1/4" x 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED SURVEYOR #35999 IN PLACE OF THE 1/2" REROD THAT CURRENTLY MARKS THE CORNER.

N20°E SPIKE AND LIV. CO. REMON TAG IN WEST SIDE OF 10" CEDAR 95.13'  
S85°E SPIKE AND LIV. CO. REMON TAG IN SOUTH SIDE OF UTILITY POLE 52.12'  
S35°E SPIKE AND LIV. CO. REMON TAG IN SOUTH SIDE OF 36" POPLAR 51.06'  
N15°W SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF 40" OAK 149.02'

Signed by [Signature] Date 10-16-2000

Surveyor's Michigan License No. 35999



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975

REVISED JAN., 1983  
REVISED OCT., 1995

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

DEED GROUP 4-19-2000 CO. REP VED