

# SURVEY & REMONUMENTATION

FEB 26 2001

FILED

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

LIVINGSTON

(County)

1. Public Land Survey

Located In: Corner Code #

T3N R3E

E-05

T R

T R

T R

T R

T R

T R

T R

2. Property Controlling  
in Section

3. Miscellaneous

Property in Sec.

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, JACK K. SMITH, in a field survey on OCTOBER 11, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1825 SYLVESTER SIBLEY SET POST 7.92'  
BLACK ASH 8" N37 1/2°W 7.92'  
MAPLE 8" S42 1/2°E

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

THE EXISTING CORNER IS A MAG NAIL AT THE INTERSECTION OF THE CENTER LINE OF THE RAILROAD TRACKS (E/W) WITH THE CENTER LINE OF NICHOLSON ROAD (PAVED).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
E-05 SOUTHEAST CORNER SECTION 8, T3N, R3E, HANDY TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  
FOUND MAG NAIL AT THE INTERSECTION OF THE CENTER LINES OF THE RAILROAD AND NICHOLSON ROAD.

N26°W 1" PIPE WITH LIVINGSTON COUNTY REMON BRASS WITNESS CAP 55.85'  
S26°E 1" PIPE WITH LIVINGSTON COUNTY REMON BRASS WITNESS CAP 59.13'  
S25°W SPIKE AND LIV. CO. REMON TAG IN EAST SIDE OF UTILITY POLE 151.92'  
N25°E SPIKE AND LIV. CO. REMON TAG IN WEST SIDE OF 6" ASH 63.31'  
N50°W SPIKE AND LIV. CO. REMON TAG IN SOUTH SIDE OF 48" OAK 112.18'

Signed by

Date 10-16-2000

Surveyor's Michigan License No. 35999

2000 OCT 30 A 9:22

NANCY HAVILAND  
REGISTER OF DEEDS  
LIVINGSTON COUNTY, MI.  
48043

LSC #1342m

Register of Deeds Stamp & File Number

| A  | B  | C | D  | E | F  | G | H  | I | J  | K | L  |
|----|----|---|----|---|----|---|----|---|----|---|----|
| 1  |    |   |    |   |    |   |    |   |    |   |    |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |
| 3  |    |   |    |   |    |   |    |   |    |   |    |
| 4  |    |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |
| 5  |    |   |    |   |    |   |    |   |    |   |    |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |
| 7  |    |   |    |   |    |   |    |   |    |   |    |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |
| 9  |    |   |    |   |    |   |    |   |    |   |    |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |
| 11 |    |   |    |   |    |   |    |   |    |   |    |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |
| 13 |    |   |    |   |    |   |    |   |    |   |    |



P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

PEER GROUP ON 9202000 CO. REP VED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN. 1983  
REVISED OCT. 1985