

FEB 25 1999

SECTION

FILED

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

LIVINGSTON

(County)

Located in:

Corner Code #

1. Public Land Survey

T. D.

T R

T. R.

T R

2. Property Controlling in Section

S T D

§ T R

3. Miscellaneous

811 / 14 T3N R5E

Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, MARY A. BARNWELL, in a field survey on AUGUST 17, 1928, do hereby state that under requirements of D.A. 74, Michigan D.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of law; established, re-established, commented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

THE GLO DID NOT SET THIS CORNER BECAUSE IT FELL IN A POND

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

COMPUTED A POSITION EQUIDISTANT TO I-05 AND K-05 ON A LINE EXTENDED WESTERLY FROM K-05 THROUGH A FOUND IRON AND FENCE CORNER AS SHOWN ON BOSS ENGINEERING SURVEY #89492. (NOTE: THIS POSITION FOR J-05 FALLS 0.37 FEET EAST AND 19.63 FEET SOUTH OF THE BOSS ENGINEERING COMPUTED LOCATION AS SHOWN ON THE ABOVE - REFERENCED DRAWING).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

005

002 (2 OF 2) EASTERLY ACCESSORY WITNESS FOR THE SOUTH 1/4 CORNER SECTION 11, NORTH 1/4 CORNER SECTION 14, T3N, R5E OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN: SET 1" X 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION WITNESS CORNER BRASS CAP WITH SURVEYOR #35999 DISTANT 250.00 FEET EASTERLY OF J-05.

N15°E	NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE 10" MAPLE	74.30"
N50°E	NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE 5" MAPLE	40.08"
S60°W	NAIL WITH LIVINGSTON COUNTY REMON TAG IN EAST SIDE 3" ASH	17.61"
S01°W	NAIL WITH LIVINGSTON COUNTY REMON TAG IN EAST SIDE 4" POPLAR	52.26"

Signed by [Signature] MAURICE W

Date. 10/1/98

Surveyor's Michigan License No. 33971



RECEIVED NEW MEXICO
RECEIVED JUL. 1965
RECEIVED OCT. 1965

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 8-5-98 CO. REP LED