

SURVEY &
REMONUMENTATION

FEB 26 2001

FILED

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

LIVINGSTON
(County)
1. Public Land Survey Located In: T3N R5E Corner Code # E-07
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

2000 AUG 29 A 9 30

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC #1261m
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, CHARLES E. GARLOCK, in a field survey on JULY 10 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1823 S. SIBLEY SET POST
BLACK OAK 18" N 85° E 11.88'
SUGAR MAPLE 10" N 86° W 6.60'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND MONUMENT BOX IN CENTER OF LATSON ROAD BUT NO IRON COULD BE FOUND. THE MONUMENT BOX IS IN LINE WITH THE CENTER LINE OF ALL FOUR ROADS. MEASUREMENTS AND ANGLES TURNED NORTH, EAST AND WEST CORRESPOND WITH RECORDS FROM 1968 AND 1969.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


E-07 NORTHEAST CORNER SECTION 20, T3N, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
SET 1 1/4" X 36" BREAKAWAY STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEYOR #14762 IN EXISTING MONUMENT BOX.

S80°E SP&TAG N/S 12" ELM
S80°W SP&TAG N/S 12" HICKORY
S85°W SP&TAG N/S 12" HICKORY
N55°W SP&TAG S/S 10" PINE
CENTERLINE OF LATSON ROAD & 3' SOUTH OF CENTERLINE OF BROPHY ROAD.

110.92'
62.92'
97.15'
68.86'

Signed by Charles E. Garlock Date 7-21-00

Surveyor's Michigan License No. 14762



P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

PEER GROUP ON 3-15-2000 CO. REP JED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 22, 1971
REVISED MAY 14, 1978
REVISED JAN. 1983
REVISED OCT., 1995