## SURVEY & REMONUMENTATION

FEB 26 2001

FILED

LINGSTON   Located In:   Corner Code #     NAMC HAVILAND	<u> የተ</u> ለተፈ	LAND COR	NER RECORDATION INTERPRETATION INTER	ON CERTIFICATE Mich. P.A. 1970			
1. Public Land Survey  T. R. T. T. R. T. T. R. T. T. R. T. T. R. T. T. R. T. T. R. T. T. R. T. T. R. T.	SECTION For corners in	ting rod			7000 AUG 2	1E # A I P	
1. Public Land Survey  T. N. R. T. T		Located In:	Corner Code #		MANCY I	HAVILAND	
2. Property Controlling S. T. R. S. T.		TR TR	F-09		REGISTER LIVINGSTÖN	COUNTY. MI.	#
5. Private Claims  1. CHARLESE CARLOCK., in a field survey on JULY 10, 2000. do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Burana of Land Management or by a decree of a Court of Law and of that the corner points mentioned in line 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-enablished, monumented, recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, rang be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  GLO 1823 S. SIBLEY SET POST BLACK OAK 18° S 48° E 20.46° WHITE OAK 15° N 12° E 25.74′  B. Description of corner evidence found and/or method applied in restoring or vecestablishing corner.  FOUND 5/8° IRON ROD NEXT TO A 1 1/2° STEEL ANGLE BED RAIL ON AN EAST-WEST FENCE LINE ABOUT 49' NORTH OF THE CONSTRUCTION CENTERLINE OF M-59.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  F-09 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  F-190 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  F-190 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  F-190 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  F-190 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  F-190 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  F-190 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  F-190 SOUTH 1/4 CORNER SECTION 21, TSN, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:	in Section S_ 3. Miscellaneous S_	TR TR TR TR		q(			lum ber
I. CHARTESE GARLOCK. in a field survey on ULY 10.2000. do hereby state that under requirements of PEA. 74, Medispa P. Ao 1970, the contrepoints mentioned in line 3 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Burson of Land Management of by a decree of a Court of Law and by that the corner points mentioned in line 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, menumented, recovered, found as expressed on this certificase.  A. Description of original monument and accessories and/or subsequent restoration:  GLO 1823 S. SIBLEY SET POST  BLACK OAK 18° S 48° E 20.46′  WHITE OAK 15° N 12° E 25.74′  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  FOUND 5/8° IRON ROD NEXT TO A 1 1/2° STEEL ANGLE BED RAIL ON AN EAST-WEST FENCE LINE ABOUT 49' NORTH OF THE CONSTRUCTION CENTERLINE OF M-59.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  F-09 SOUTH 1/4 CORNER SECTION 21, T3N, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:  SET 1 1/4" 3 6° STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEY H4762 WHERE OLD IRON WAS FOUND.  N45°W NORTHEAST CORNER OF HOUSE  N60°W SPEATAG NS 12" PINE  N60°W SPEATAG WS 12" PINE	4. Lot No, Recorded Pl 5. Private Claims	at		- <sup>1</sup>	A B C D E F	G H I J	K L
A. Description of original monument and accessories and/or subsequent restoration:  GLO 1823 S. SIBLEY SET POST BLACK OAK 18" S 48" E 20.46' WHITE OAK 15" N 12" E 25.74'  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  FOUND 5/8" IRON ROD NEXT TO A 1 1/2" STEEL ANGLE BED RAIL ON AN EAST-WEST FENCE LINE ABOUT 49' NORTH OF THE CONSTRUCTION CENTERLINE OF M-59.  C. Description of monament for corner and accessories established to perpetuate locating the position of the corner: F-09 SOUTH 1/4 CORNER SECTION 21, T3N, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN: SET 1 1/4" X 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEYS WITH 1/40 WHERE OLD IRON WAS FOUND.  N45"W NORTHEAST CORNER OF HOUSE 73.82' N60"W SP&TAG S/S 12" PINE 73.82' N40"E SP&TAG S/S 12" PINE 74.82' N40"E SP&TAG S/S 12" PINE 74.	of P.A. 74, Michigan P.A. of 1970, the regulations and rules therefore as reduced between the Interior, Bureau of Logiats mentioned in lines 3, 4 and 5 at Surveyors or by a Decree of a Court of Libelow:	corner points mentioned in i ired in the current manual and Management or by a dec pove were in conformance w aw; established, re-established	of survey instructions of cree of a Court of Law and with the rules of the Michi d, monumented, recovered,	conformance with 5 the United States /or that the corner gan Board of Land 7 found as expressed 8	19 20 -2	5 15 14	13
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  FOUND 5/8" IRON ROD NEXT TO A 1 1/2" STEEL ANGLE BED RAIL ON AN EAST-WEST FENCE LINE ABOUT 49' NORTH OF THE CONSTRUCTION CENTERLINE OF M-59.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  F-09 SOUTH 1/4 CORNER SECTION 21, T3N, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN: SET 1 1/4" X 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEY. #14762 WHERE OLD IRON WAS FOUND.  N45°W NORTHEAST CORNER OF HOUSE N60°W SP&TAG S/S 12" PINE N60°W SP&TAG S/S 12" PINE N60°W SP&TAG S/S 12" PINE N60°W SP&TAG S/S 12" PEAR N20°E SOUTHWEST CORNER POLE BARN S CENTERLINE OF M-59  Signed by  Date  7-21-20  CHARLES E.  GARLOCK SURVEYOR N6. 14762	on this certificate.			1: 12	1 31 32 3	+++-	36
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-09 SOUTH 1/4 CORNER SECTION 21, T3N, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN: SET 1 1/4" X 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEY #14762 WHERE OLD IRON WAS FOUND.  N45°W NORTHEAST CORNER OF HOUSE N60°W SP&TAG S/S 12" PINE N60°W SP&TAG S/S 12" PINE N20°E SOUTHWEST CORNER POLE BARN S CENTERLINE OF M-59  Signed by  MALES  Date  7-2/-W  The CONSTRUCT OA 1 1/2" STEEL ANGLE BED RAIL ON AN EAST-WEST FENCE LINE ABOUT 49' NORTH CONSTRUCTION OF MICHIGAN: THE CONSTRUCTION OF M-59.  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  F-09 SOUTH (CONSTRUCTION OF M-59)  120.58' 73.82' 73.82' 73.82' 73.82' 73.82' 73.82' 73.82' 74.82' 75.	GLO 1823 S. SIBLEY SET POST BLACK OAK 18" S 48° E 20.	46'	subsequent restoration:				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  F-09 SOUTH 1/4 CORNER SECTION 21, T3N, R5E, OCEOLA TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN: SET 1 1/4" X 36" STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEYS #14762 WHERE OLD IRON WAS FOUND.  N45°W NORTHEAST CORNER OF HOUSE N60°W SP&TAG S/S 12" PINE N40°E SP&TAG W/S 12" PEAR N20°E SOUTHWEST CORNER POLE BARN S CENTERLINE OF M-59  Signed by  Date 7-21-00  Tentory  CHARLES E.  GARLOCK PROFESSIONAL SURVEYOR NO.  14762					r fence line ai	3OUT 49' NOR	TH OF
F-09 SOUTH 1/4 CORNER SECTION 21, T3N, RSE, OCEOLA TOWNSHIP, LIVINGSTON COUNTY REMONUMENTATION BRASS CAP STAMPED WITH SURVEY #14762 WHERE OLD IRON WAS FOUND.  N45°W NORTHEAST CORNER OF HOUSE N60°W SP&TAG S/S 12" PINE N40°E SP&TAG W/S 12" PEAR N20°E SOUTHWEST CORNER POLE BARN S CENTERLINE OF M-59  Signed by  Date 7-2/-00  TABLES E.  GARLOCK PROFESSIONAL SURVEYOR NO. 14762	THE CONSTRUCTION CENT	ERLINE OF M-59.					
N45°W NORTHEAST CORNER OF HOUSE N40°E SP&TAG S/S 12" PINE N40°E SP&TAG W/S 12" PEAR N20°E SOUTHWEST CORNER POLE BARN S CENTERLINE OF M-59  Signed by	F-09 SOUTH 1/4 CORNER SE SET 1 1/4" X 36" STEEL PIPE	ECTION 21, T3N, R3E, EWITH LIVINGSTON			OUNTY, MICHIG SS CAP STAMPE	IAN: D WITH SURV	ÆYOR
Signed by Walled Date 7-21-00 # GARLOCK PROFESSIONAL SURVEYOR No. 14762	N60°W SP&TAG S/S 12" PIN N40°E SP&TAG W/S 12" PE/ N20°E SOUTHWEST CORNI	E Ar			73.82' 59.68' 161.40'		To be the second
As A	Signed by Marles	Saff	Date	7-21-00	1 1	GARLOCK	PUREYOR *

Surveyor's Michigan License No. 14762