1993

CO	ĸ,	A	Ŕ	P	r c	1	ترج	1		١	J
فانك	1	/ }		ėÈ	ŝ	€.	⋰	ş	البرية	å.	,

LAND CORNER RECORDATION CERTIFICATE

For corners in		Located In: Corner Code ## Located In: Corner Code ## Corner Code ## Living Requirement of Act 74, Mich. P.A. 1978 LL NAMCY HAVILAND RECISTER OF DELUS RECISTOR COUNTY. MI LIVINGST 08843								
	LIVINGSTON	Located In:	Corner Code ≠#	NANCY HAS DELLE HI						
(County)		2002103 111.	00111010000-44	REGISTON COUNTY						
1.	Public Land Survey	T R T R	K_12	Flaires VBBus						
		T R · T R								
2.	Property Controlling	S T R		L.S.C.# 68m						
	in Section	S T R								
3.	Miscellaneous	S T R	·	Register of Deeds Stamp & File Number						
	Property in Sec.	S T R		register of Deeds Stamp α File Rumber						
4.	Lot No,	Recorded Plat		A B C D E E C II I I I I I						
5.	Private Claims			ABCDEFGHIJKL						

, ₁₉ <u>9</u>3 Donald G. Richards a field survey on October 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Sylvester Sibley, June 9th, 1823 Black Ash 14 N 89 1/2 W 32 Black Ash 12 S 72 E 25

q 10

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found bolt in monument box (see reverse side for research and investigation summary)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

ion of monument for corner and accessories established to perpetuate locating the position of the corner:

Re-set with 1 1/4" x 36" iron pipe w/brass cap stamped "Livingston; County Remonumentation Corner" in Monument Box
2 45 W 52.25' nail/LCWT* in E face 16" Willow
48.93' nail/LCWT in S face 17" Poplar
28.93' nail/LCWT in SE face 6" Elm
29. RICHARDS
20. SURVEYOR
10. 24614

DONALD G. RICHARDS

Signed by _ Surveyor's Michigan License No. 24614 APPROVED by Livingston County Monumentation Peer Group 11-23-93 REVISED MAY 14. 1975

REVISED JAN., 1983

СОНОСТАН К-12

Deputy Surveyor Sylvester Sibley set a wood post to establish this point on June 9th, 1823.

Information furnished by C.E. Garlock identifies the corner material as a 1/4" x 16" square iron in 1966. Later surveys by Boss in 1978, 1980, and 1987 identify a 1/2" Iron rod in monument box. However, in Boss'90 the corner is a found bolt in monument box.

On October 19, 1993, fieldcrews recovered a bolt in monument box, consistent with the most recent surveys by Boss'90. Its position relative to corners K-11 and K-12 is substantially as indicated in surveys by Boss'78 and '90.

Donald G. Richards, PS 24614 November 18, 1993