

SURVEY & REMONUMENTATION

FEB 25 1999

FILED

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corner in

LIVINGSTON
(County)

located in:

Corner Code #

1. Public Land Survey

T4N R5E

G-11

2. Property Controlling
in Section

§

T R

§

T R

3. Miscellaneous

§

T R

Property in Sec.

§

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

1998 OCT 20 P 1:22

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC938M

Register of Deeds Stamp & File Number

I, MARY A. BARNWELL, in a field survey on SEPTEMBER 17, 1998 do hereby state that, under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1823 SIBLEY SET POST

YELLOW OAK 18 N52W 21 (13.9')

YELLOW OAK 14 S80E 67 (44.2')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A 1/2" REROD AT THE INTERSECTION OF CENTER LINES OF FAUSSETT ROAD AND MACK ROAD. THIS CORNER POSITION AGREES WELL WITH WITNESSES OF RECORD SINCE 1958.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-11 CORNER COMMON TO SECTIONS 27, 28, 33 AND 34, T4N, R5E, DEERFIELD TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:

RESET FOUND 1/2" IRON WITH 1 1/4" X 36" BREAKAWAY STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP WITH SURVEYOR #35999 @ 1/2 FOOT BELOW THE SURFACE OF MACK ROAD IN MONUMENT BOX OF

S50°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE 45" OAK 41.87'
N65°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN SOUTH SIDE 36" HICKORY 65.39'
N30°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE UTILITY POLE 98.13'
N55°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN SOUTH SIDE 30" DBL. OAK 58.78'

Signed by Mary A. Barnwell

Date 10/1/98

Surveyor's Michigan License No. 33971



P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 9-2-98 CO. REP VED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JULY 25, 1991
CORDED BY RECD
CORDED JUL 25
RECD OCT 1998