

SURVEY & REMONUMENTATION

FEB 25 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

LIVINGSTON
(County)

Located In:

Corner Code #

1. Public Land Survey

T4N R5E

E11

2. Property Controlling
in Section

§

T R

§

T R

3. Miscellaneous

§

T R

Property in Sec.

§

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

1998 OCT 20 P 1:22

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC940M

Register of Deeds Stamp & File Number

I, MARY A. BARNWELL, in a field survey on SEPTEMBER 17, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1823 SIBLEY SET POST
WHITE OAK 14 S06W 27 (17.8')
WHITE OAK 12 N01W 55 (36.3')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A RAILROAD SPIKE AT THE INTERSECTION OF CENTER LINES OF FAUSSETT ROAD AND ARGENTINE ROAD (BOTH PAVED). THIS CORNER POSITION AGREES WELL WITH WITNESSES OF RECORD SINCE 1976.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-11 CORNER COMMON TO SECTIONS 26, 27, 34 AND 35, T4N, R5E, DEERFIELD TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:

RESET FOUND RAILROAD SPIKE WITH 1 1/4" X 36" BREAKAWAY STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP WITH SURVEYOR #35999 @ 1/2 FOOT BELOW THE SURFACE OF THE ROAD IN MONUMENT BOX.

N53°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN SE SIDE 26" ELM 94.07'
S38°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE 22" ELM 65.39'
N30°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE UTILITY POLE 98.13'
N55°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN SOUTH SIDE 30" DBL. OAK 58.78'

Signed by Mary A. Barnwell

Date 10/1/98

Surveyor's Michigan License No. 33941



P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

PEER GROUP ON 9-2-98 CO. REP JED

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JULY 21, 1998

EXPIRED NOV 1995
EXPIRED JUL 1998
EXPIRED OCT 1998