

FEB 25 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in

LIVINGSTON
(County)

Located In:

Corner Code #

1. Public Land Survey

T4N D5E

J-11

T R

T R

T R

2. Property Controlling
in Section

§

T R

§

T R

3. Miscellaneous

§

T R

Property in Sec.

§

T R

4. Lot No. , Recorded Plat

5. Private Claims

1998 OCT 20 P 1:22

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC942M

Register of Deeds Stamp & File Number

MARY A. BARNWELL, in a field survey on SEPTEMBER 17, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1823 SIBLEY SET POST
YELLOW OAK 18 N79W 18 (11.9')
HICKORY 6 N57E 10 (6.6')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A 1/2" REROD ON THE CENTER LINES OF FAUSSETT ROAD (GRAVEL) WITH A TREE ROW TO THE SOUTH. THIS CORNER POSITION AGREES WELL WITH WITNESSES OF RECORD SINCE 1976.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-11 SOUTH 1/4 CORNER SECTION 26 / NORTH 1/4 CORNER SECTION 35, T4N, R5E, DEERFIELD TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN:
RESET FOUND 1/2" IRON WITH 1 1/4" X 36" BREAKAWAY STEEL PIPE WITH LIVINGSTON COUNTY REMONUMENTATION BRASS CAP WITH SURVEYOR #35999 @ 1/2 FOOT BELOW THE SURFACE OF FAUSSETT ROAD.

N05°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN EAST SIDE 38" OAK 23.97'
N62°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN SOUTH SIDE 24" OAK 39.22'
S29°E NAIL WITH LIVINGSTON COUNTY REMON TAG IN EAST SIDE 30" OAK 37.47'
S05°W NAIL WITH LIVINGSTON COUNTY REMON TAG IN WEST SIDE 24" OAK 28.12'

Signed by Mary A. Barnwell

Date 10/1/98

Surveyor's Michigan License No. 33971

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

PEER GROUP ON 9-2-98 CO. REP JED

FORM APPROVED BY MICHIGAN BOARD OF PROFESSIONAL SURVEYORS

DESIGNED BY HES
DRAWN BY JES
CHECKED BY JES

