LAND	CORNER	RECO	RDA	TION	CER	TIFI	CATE
Filing	Requirem	ient of	Act	74, N	lich.	P.A.	1970

Dr corners in Livingston	Located In:	Corner Code ≠	NANCY HAVILANI REGISTER OF DEL LIVINGSTON COUNTY, HJ 48843
- Public Land Survey	T_4NR_6E	F-11	
	T R T R		
 Property Controlling in Section 	S T R S T R		L.S.C.#421m
 Miscellaneous Property in Sec. 	S T R S T R		Register of Deeds Stamp & File Number
Lot No, F	Recorded Plat		<u>A B C D E F G H I J K</u>

Edward Anderson, in a field survey on _ <u>June 6</u> . 19 <u>95</u> hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the irrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a purt of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:

OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G.L.O. Notes dated: April 5, 1823 G.L.O. Witnesses: W. Oak 30" N82"E 48 Lks W. Oak 30" S29°W 54 Lks

Additional historical data on back

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rerod. Fit witnesses by Boss, Albright, Anderson, and Richard Smith

in the second Fillen and the second 00T (1) 1995

ran e e

ित्तव हुन्छ

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11	<u>N 1/4 COR. SEC. 33 T4N-R6E</u>	
С. С. С.	Set 1 1/4" x 36" iron pipe with brass cap (L 13' - north of centerline of Faussett Road N 08°E 22.69 Spike E/S 12" Elm	iv. Co. Mon. Cor.)
	S25°W 49.26' Spike E/S 12" Hickory	
• •	S44°W 72.53' Spike W/S 12" Oak	
··· •	N57°W 35.15' Spike S/S 12" Elm	P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
		PEER GROUP ON 5-3-95 CO. REP JED
ned by	* EDWARD E. *** ANDERSON ** SURVEYCA & 5	Date <u>July 5, 1995</u>
·	chigan License No	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 23, 1971 Revised May 14, 1975
	MAR CUIVEYOF & PICE	REVISED JAN , 1983

	<u>A</u>	в	С	D	E	F	G	н	Ļ	<u> </u>	L	М
2		6—		5		[₄		3	;	2		
3		ļ		I]					L		
4	ļ_	7		 8		 9 —	L_1	 		 1	Ļ,	
5			[_							
6		8	<u> </u> _1	 7	1	6		 5—-	<u> </u>	4	1	34
7				ļ		ļ						
8	Ļ_,	9	2	 0	2	 1	2	2	2	3-—	-2	4
9		ļ	L.		_			L		L		
10	<u> </u>	 10	_2	9	2	8	2	,	2	6		5
11		<u> </u>										
12		 \$1	3	2	3	[3	3	4	3	5	3	6
	1	1		1		1						1

FILER

JUL 14 9 45 AH '95

NANCY HAVILANI RECISTER OF DEL LIVINGSTON COUNTY, MJ 98843



EDWARD E. ANDERSON, P.S., P.E. RICHARD F. FRANK, P.S. BRIAN R. SHALTZ, C₁S.T. Members of: Michigan Society of Professional Surveyors American Congress on Surveying and Mapping American Society of Civil Engineers

and an and the second secon

and and the set we and the bat the baseling of the

401 S. Leroy St. Fenton, Michigan 48430-2164 (313) 629-8974 FAX (313) 629-9069

SUMMARY

April 27, 1995

F-11 N 1/4 CORNER SECTION 33, T4N-R6E, TYRONE TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN.

Found 1/2" Rerod 13' $\frac{1}{2}$ north of the centerline of Faussett Road (gravel)

Checked and measured to witnesses we found. Found 6 of 8 of Boss witnesses and they checked, pages 11, 12, and 20 this dossier. Found 2 of 3 of Albright witnesses, page 13 this dossier. Found 2 of 4 of Anderson witnesses and they checked, page 16 this dossier. Found 1 of 3 of Richard Smith witnesses and they checked, page 18 this dossier.

Distance from the N 1/4 corner to the N.E. corner of said Section 33 is 2649.20' on Richard Smith survey, page 17 this dossier, and 2648.98' on Anderson survey, page 16 this dossier, and 2649.12' on Boss survey, pages 15 and 19, this dossier.

Distance from the N 1/4 corner to the NW corner of said Section 33 is 2648.44' on Richard Smith survey page 17 this dossier, and 2648.45' on Albright survey, page 14 this dossier.

Made a clean sweep of immediate area and found no additional corner or irons.

Gravel roads running east and west. Roads are flat in both directions.

Terrain is wooded to the north and open to the south. House to the N.W., S.E., and S.W.

Tree line to the south.

Poor location for G.P.S.

Came to the conclusion that the $1/2^{"}$ rion we found is the correct N 1/4 corner of said Section 33.



santia and Dealmann - Jup