			FILED	<b>v</b> . <i>i</i>
(County)  1. Public Land Survey  2. Property Controlling S in Section S  3. Miscellaneous S	LAND CORNER RECORDATION         Filing Requirement of Act 74, Million         -ocated In:       Corner Code =##         T	ich. P.A. 1970	AUG IS I 15 PM SANCY HAVE AN BISTER OF DEL TABSTON COUNTY. 48843 L.S.C.#226m ister of Deeds Stamp & F	м н м н
	August 3, survey on <u>April 25,</u> 19		$\begin{array}{c} A  B  C  D  E  F  G \\ 2 \\ -6 \\ -7 \\ -6 \\ -7 \\ -7 \\ -8 \\ -9 \\ -1 \\ -7 \\ -8 \\ -9 \\ -1 \\ -1 \\ -7 \\ -1 \\ -7 \\ -8 \\ -9 \\ -1 \\ -7 \\ -7$	H I J K L M 3
do hereby certify that under requirements of in lines 1 and 2 above were in conforman current manual of survey instructions of th Management or by a decree of a Court of La above were in conformance with the rules of Court of Law; established, re-established expressed below:	P.A. 74, Michigan P.A. of 1970, the corner point ce with regulations and rules therefore as req e United States Department of the Interior, Bur w and/or that the corner points mentioned in line of the Michigan Board of Land Surveyors or by a ed, monumented, re-monumented, recovered in the same town and range, may be reco	s mentioned uired in the eau of Land es 3, 4 and 5 Decree of a , found as	$\begin{array}{c} 3 \\ 6 \\ -18 \\ 7 \\ 7 \\ 8 \\ -19 \\ 20 \\ -21 \\ -29 \\ 9 \\ 10 \\ -30 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -29 \\ -28 \\ -$	5 14 13 2 23 24 7 26 25 4 35 36
G.L.O. NOTES Dated Apri G.L.O. WITNESSES W. Oal		SUR REMONU	NEY & MENTATION	
Deputy Surveyor Sylvester ADDITIONAL HISTORICAL DATA	Sibley 1823 - 1825		2 6 1994 MISSION	
	ind and/or method applied in restoring or ail in center. Fit witnesses			
P.A. 345 1990, APP PEER GROUP ON	ROVED BY LIVINGSTON COUNTY)			
H-13 S 1/4 CORNER SECTION Set 1 1/4" x 36" Bre Corner) 2' - South N73°E 58.46' Spike S S59°E 40.67' Spike N S34°W 40.22' Spike W N71°W 63.79' Spike S West 142.14' 5/8" F	akaway pipe with Brass Cap (L of Parshallville Road /S 24" Oak W/S 12" Maple //S 14" Oak //S 12" Butternut	ivingston C APPROVED MONUMENT JUNE 29,	ounty Monument BY LIVINGSTON COU ATION PEER GROUP 1994	ΝΤΥ
Signed by	11495 FROMESA 11-95		9 NICHIGAN STATE BOARD OF LAND S	URVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983



EDWARD E. ANDERSON, P.S., P.E. RICHARD F. FRANK, P.S. BRIAN R. SHALTZ, C.S.T. Members of: Michigan Society of Professional Surveyors American Congress on Surveying and Mapping American Society of Civil Engineers

401 S. Leroy St. Fenton, Michigan 48430-2164 (313) 629-8974 FAX (313) 629-9069

TUN REE Hris

С-С-

11495 Uneyor &

June 13, 1994

## SUMMARY

## H-13 SOUTH 1/4 CORNER SECTION 34, T4N-R6E, TYRONE TOWNSHIP LIVINGSTON COUNTY, MICHIGAN.

Found 1 1/2" Pipe with nail in center  $2'^+$  south of Parshallville Road (gravel)

Measured to witnesses we found. Found all of Richard Smith witnesses and they checked, Pages 10 and 14, this dossier. Found two of Bosses witnesses and they checked, Page 8 and 17, this dossier.

Found 5/8" Rerod 142.14' West of the South 1/4 Corner and it checked. Boss surveys and Richard Smith Survey, Pages 9, 10 and 13, this dossier. Boss and Smith called this iron the N 1/4 corner of Section 3, T3N-R6E, and also shown Boss ACT 74, Page 18, this dossier.

Distance from S. E. corner to the South 1/4 Corner of said Section 34 is 2655.37; Anderson calculations using the recorded plat of Lake Tyrone Estates #1, Liber 5, Pages 15 and 16, and Lake Tyrone Estates #5, Liber 5, Pages 35 and 36, L.C.R., Pages 15, 16, 19, and 20, this dossier.

Distance from S.W. corner to the South 1/4 corner of said Section 34 is 2657.07 as measured by E. E. Anderson on 6/7/94.

Made a clean sweep of immediate area and found no other additional corners or irons.

Found old tree and fence line to the North. Nothing to the South.

Terrain is open to the North and wooded to the South. House to the Northeast and House to the S.W.

Parshallville Road (gravel) is fairly flat to the East and to the West.

Came to the conclusion that the 1 1/2" Pipe we found is the correct OF Michaeler South 1/4 Corner of said Section 34.

Edward E. Anderson

P.S. #11495

Architectural, Construction, Property and Drainage Surveys Civil Engine. > • Land and Site I • Mortgage Inspe I Reports