## SURVEY & REMONUMENTATION

## FEB 26 2001

## SECTION

5

Private Claims

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Livingston Located In: Corner Code ## 2000 NOV 15 A 9:29 (County) NANCY HAVILAND REGISTER OF DEEDS 1-7 T 4N 8 6E Public Land Survey 1 \_\_\_\_ R \_\_ LIVINGSTON COUNTY, ML R Т 48843 Т R **Property Controlling** s Т \_\_\_\_ R 2. LSC #1356m \_\_\_\_T \_\_\_\_ R \_\_\_ s in Section Ũ \_\_\_\_ T \_\_\_\_ R \_\_ Miscellaneous S 3 **Register of Deeds Stamp & File Number** s R Property in Sec. т Lot No. \_\_\_\_, Recorded Plat \_\_ 4

 $\label{eq:linear_line$ 

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

|    | A          | B        | c   | D        | E        | F        | G           | н        | <u> </u> | ĸ  | L           | M |
|----|------------|----------|-----|----------|----------|----------|-------------|----------|----------|----|-------------|---|
| 2  |            | 6—       | ļ   | <br>5 —  |          | <br>4    | <b> </b>    | 3        |          | 2  |             | _ |
| 3  | Ĺ          | 1_       | L   | I        | <b>\</b> | <b>\</b> | <b> </b>    | <u> </u> | L        |    | <b>└</b> ─↓ | _ |
| 4  | _          | <br>?    | L   | 8        | -        | ļ        | +1          | 0        | L-1      | 1  | $\vdash$    | 2 |
| 5  |            | L        |     | L        |          |          | _           |          | <u> </u> |    |             |   |
| 6  | <b>–</b> 1 | 8        | L-1 | ا<br>۲   | -1       | 6        |             | 5        | 1        | 4— | 1           | з |
| 7  | L          | L        | L   | <b> </b> | L        |          | <u> </u>    | -        | _        |    |             |   |
| 8  |            | )<br>9   | -2  | )<br>0   | 2        | <br> 1   | <u> </u> _; | 2        |          | 3  | -2          | ▲ |
| 9  |            |          | L.  | ļ        | L        | <b> </b> | ļ           | L        |          |    | _↓          |   |
| 10 |            | 0        | -2  | <br> 9   | 2        | 8        | -2          | 7        | -2       | 6— | -2          | 5 |
| 11 | L          | <u> </u> | ļ   | <u> </u> | I        | L        | L           | ļ        |          |    |             |   |
| 12 |            | <br>1    | -3  | 2-       | 3        | 3-       |             | 4        |          | 5  | -3          | 6 |
| 13 | L.         | L        | L   | L        | L        | L        |             | <u> </u> |          |    |             |   |

FILED

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-7 Found 1/2" Iron

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-7 Southwest corner Section 14, T4N-R6E Set 1 1/4" x 36" Iron Pipe w/Brass Cap (Liv. Co. Mon. Cor.) N 65° E, N 20° W, 54.05' Set Nail and Liv. Co. Remon Tag in South face 32" Oak 61.01 Set Nail and Liv. Co. Remon Tag in East face 26" Walnut N 50° W, 61.38 Set Nail and Liv. Co. Remon Tag in South face 30" Walnut Set Nail and Liv. Co. Remon Tag in North face Elm cluster S 70° W. 78.67 E OF MICHIQ P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY Ĝ PEER GROUP ON 6.21.00 00. REP JED EDWARD E ÷ ANDERSON SURVEYOR ENGINE 00 10 Signed by 1 Date 9*6* ~ ~ ~ ~ ~ Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan.. 1983