

**SURVEY &
REMONUMENTATION**

FEB 26 2001

FILED

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Livingston

(County)

Located In:

Corner Code #

- | | | |
|---------------------------------------|--------------------------|------------|
| 1. Public Land Survey | T <u>4</u> N R <u>6E</u> | <u>L-9</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling
in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous
Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

2000 NOV 15 A 9:29

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

LSC #1364m

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		18		19		20		21		22
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Ed Anderson in a field survey on 10-18, 19 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:


B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-9 Found 3/4" Pipe w/Cap No. 23518

**P.A. 348 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 9-20-00 CO. REP JED**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**L-9 South 1/4 corner Section 24, T4N-R6E
Set 1 1/4" x 36" Iron Pipe w/Brass Cap (Liv. Co. Mon. Cor.)
N 10° W, 25.44' Set Nail and Liv. Co. Remon Tag in East face 28" Oak
N 45° W, 29.15' Set Nail and Liv. Co. Remon Tag in Southwest face 18" Oak
S 15° W, 33.03' Set Nail and Liv. Co. Remon Tag in East face group Cherry
East, 20.30' Found 1/2" Iron**



Signed by

Date

10/19/00

Surveyor's Michigan License No. 1149