PA. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 12-11-98 CO REPLED

FEB 2 5 1999

,~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	LAND COR	NER RECORDATION	CERTIFICATE	rileu	
SECTION .	Filing Requ	ulrement of Act 74, N	l		
LIVINGSTON	located in:	Corner Code #	119	8 DEC 11 , P 12: 41	4
(Courly)			£	NANCY HAVILAND REGISTER OF DEEDS	
Dublic land Survey	TAN REE	M-13	Liv	INGSTON COUNTY, MI.	
·	TR TR			, , , , ,	ŧ
	TR		, T. :	S.C.#989m	
Property Controlling S in Section S	TR TR				
Miscellaneous S Property in Sec. S	TR TR			Register of Deeds Sta	mp & File Number
Tropers at over					
4. Lot No, Recorded Plat 5. Private Claims			_ 1	ABCDRFG	HIJKLM
5. Private Claims				! - 6	-3-1-2-1-1
	,		3 		_101112
I JACK K SMITH, in a f requirements of P.A. 74, Michigan P.A. of 197	field survey on <u>DECE</u> 70, the corner points menti	MBER 11, 19 98 do hereb oned in lines 1 and 2 above wer	y state that under	1	
with regulations and rules therefore as requ	Ulion by the chirche make	and Court of Law and for that	the corner points	6 19 17 16	-151413
Department of the Interior, Bureau of Land N mentioned in lines 3, 4 and 5 above were in or Decree of a Court of Law; established, re-esta-	mformance with the rules of blished, monumented, rec	of the Michigan Board of Land overed, found as expressed belo	w:	7 20 21	222324
NOTE: Not more than 2 corners, all in the				9	++++
on this certificate.		•		10 30 29 28	-27 - 26 - 25
·				12 31 32 33	35 36
,	er e e e e e e e e e e e e e e e e e e		,	13	
A. Description of original monument	and accessories and/o	r subsequent resultation.			
GLO 1815 SET POST WHITE OAK 10 N10W 4.50	(297)		·:		
BLACK OAK 6 S85W 3.80	(250.8')		to a second		
			1.11.4.1		
B. Description of corner evidence for	ound and/or method ap	plied in restoring or reesu	n tet outland outlet.	TCUES ACT 74 OF 19	74 BY OSCAR BOSS
FOUND A 1" STEEL PIPE WES' LSC #843.	T OF A ROTTED W	VOODEN FENCE POS	I IIA 2AA WAYE IAYA	KUIIQ NOL 17 OL 17	
•					
			on of the comer:		$(1,1) \in \mathcal{M}$
C. Description of monument for corner and M-13 SOUTHEAST CORNER S			ተረግሪሞያንኤ፣ ሲጎርጎ፣ የኢነኛ፣	Y, MICHIGAN:	
M-13 SOUTHEAST CORNER S RESET FOUND 1" PIPE WITH SURVEYOR #35999 @ ½ FOOT				EMONUMENTATION	BRASS CAP WITH
S63°43'W 1" PIPE WITH LIV. S24°14'W 1" PIPE WITH LIV.					
S02°21'W 1" PIPE WITH LIV S75°26'W 1" PIPE WITH LIV	COUNTY REMORE COUNTY REMORE	N BRASS WITNESS CA NON BRASS CORNER	AP (SURVEYOR # CAP (SURVEYO	11495) 34.52'	
S02°21'W 1 1/4" PIPE WITH 1 N28°16'48"W 1" PIPE WITH 0 S16°05'36"W 1/2" REROD WA	CARSONITE POST TH CAP #35909 AN	ON S. SIDE TIPSICO! D CARSONITE POST	LAKE ROAD ON W. SIDE TIPS	41.87' SICO LK. RD. 475.88'	
Signed by Jale	(hum)	and the Land	2-10-1990	3	
	3 Kr. 6 28 6 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7	OF MICHAEL			
Surveyor's Michigan License No	The state of the s	JACK K. SMITH POFESSIONAL #	FORM APPROVED BY 1	MICHIGAN STATE BOARD OF FRO REVISED MAY 14,1978	DYESSKONAL SURVEYORS, JAN REVISED JAN., 1983 REVISED OCT., 1995
	20 3				