

SURVEY &
REMONUMENTATION

OCT 11 1994

COMMISSION

MACKINAC COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac

(County)

Located In:

Corner Code #

1. Public Land Survey

1 40N R 4W E-1 ✓

1 41N R 4W E-13

T R

T R

2. Property Controlling

S T R

in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Neil E. Hill

August 22 94

I, Neil E. Hill, in a field survey on August 22, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original set wood post by Burt 1840

12" Birch N69E 0.17 ch

11" Sugar Maple N35W 0.11 ch

Additional Mullet 1845

12" Sugar Maple S30W 0.40 ch

6" Sugar Maple S45E 0.20 ch

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1981 Stockholm dug and recovered pipe and rock 2' below surface; recorded Liber B, Page 304

1988 MDOT tied and used

1994 Found 3" brass tablet 1 foot below gravel road surface

P. Pole N62E 36.0'

5" Cedar N53W 35.7'

4" Cedar S70E 48.9'

Marker post N20W 40.6'

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 8-16-94

James H. Shaver

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted the corner in its current location.

Accepted the USFS witnesses as follows:

P. Pole N62E 36.0'

5" Cedar N53W 35.7'

4" Cedar S70E 48.9'

Marker post N20W 40.6'



Signed by Neil E. Hill P.S.

Date August 22, 1994

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

09-06-94 1CL3183

MSSR

REVISED MAY 14, 1975
REVISED JAN., 1983

D-0271