MAY 2 0 1997

MACKINAC COUNTY REMONUMENTATION CORNER

COMMISSION	i	remark of Art 74 Mich	
For corners in	riling Kequi	rement of Act 74, Mich.	RECEIVED & FILED
Mackinac (County)	Located In:	Corner Code ##	DIANE FRANKOVICH MACKINAL COUNTY PROISTS . OF DEEDS
: 1. Public Land Survey	T40N R4W	I-1	NOV 1 5 1996
	T' R		AM PM
:	T R	Sec cor common to	7[8[9]10[11]12[1[2]3]4[5]6
Property Controlling S	T R S T R	Sec's 2-3-34-35	
	S T R		
	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S R		
. Lot No, Reco	orded Plat		ટાક્ટરમપે પહેલક,
Private Claims	orded Flat		A B C D E F G HT J K
			2 6 5 4 3 2
			3
A7.3 TO TT91		1 (T) 1 (1)	4 7 - 8 - 9 - 10 - 11
Neil E. Hill , in o hereby certify that under require	a field survey on SEPTE	MBER 30 , 19 <u>9</u>	6 , 5
lines 1 and 2 above were in col	nformance with regulations a	nd rules therefore as required	in the
urrent manual of survey instructio	ons of the United States Depa	rtment of the Interior, Bureau o	of Land 7
anagement or by a decree of a Co pove were in conformance with th	urt of Law and/or that the corn e rules of the Michigan Board	er points mentioned in lines 3, 4 of Land Surveyors or by a Decr	and 5 8 19 20 21 22 23
ourt of Law; established, re-es			
xpressed below:			10 30 29 28 27 26
OTE: Not more than 4 corne	ers, all in the same town a	nd range, may be recorded	
on this certificate.			12 31 32 33 34 35
. Description of original mon	ument and accessories an	d/or subsequent restoration	n·
6" Tamarack N2 Recorded Liber B, Page 34			
: Description of corner evide	nce found and/or method	applied in restoring or rees	tablishing corner
Found F.F.S. std. monume		approa in reaconing or reco	tabilishing domain
•		re between recovered co	oner positions to the east & west.
2 1/2" x 5' concrete filled g			
10" Cedar NO		7" Tamarack	S48W 28.3'
10" Cedar S6	6E 31.8 ¹	Cedar post	The state of the s
8" Cedar S1			
Accepted corner location.			COPPTED BY THE MARKET
		S C 3	CCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE DEFICIAL CORNER UNDER P.A. 45 OF 1990 AT A MEETING
Also recorded in: T 41N,	R4W, I-13	ŀ	ELDON 9-30-96
-		established to perpetuate l	Jams H Stanger Scating the position of the corner:
Accepted corner as found.	Measurements to nails	in side of trees.	
14" Cedar N08			with OF Michigan
16" Cedar S66			MEN E
14" Cedar S14			FS HILL
7" Tamarack S48			Land Surveyor
· ————————————————————————————————————	·		No.

SEPTEMBER 30, 1996