

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Mackinac Co.

Two Corners

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 41 N. R. 11 W.	1-3 Meander Cor. South of I-3 on Lake Mich.
2. PROPERTY CONTROLLING IN SECTION	10 T. 41 N. R. 11 W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on 9/25 1969, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
I-3 Sec. Cor. placed by John Burt, D.S. Aug. 1845.

M.C. South of I-3 set by John Burt, D.S. Aug. 1845

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
I-3 Found a 1" iron pipe, placed by unknown Surveyor and a Tamarack bearing tree to North-West, in proper position. Corner lies in N-S fence line.

M.C. South of I-3
Placed on fence line, bearing South from Sec. Cor. 2-3-10-11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
I-3 Re-Witnessed Sec. Cor.

9" B. Ash S76°E 31.6'
Boulder, 4' high S45°E 5.1'

M.C. South of I-3 Placed 1" pipe with 4" aluminum cap
New bearings:

10" Cedar N65°W 5.8'
10" Cedar N39°E 22.3'

SIGNED BY Billy D. Buckler

DATE 6/14/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 0087

(SEAL)

FOR STATE AND UNITED STATES AGENCIES

SIGNED BY

DATE

APPROVED AND SIGNED BY

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.