

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Mackinac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S <u>17</u> T <u>42N</u> R <u>01W</u> S <u>17</u> T <u>42N</u> R <u>01W</u> S _____ T _____ R _____	<u>9</u> <u>12</u> _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		10		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 09/11/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 17) East 1/16 corner, Section 17. Not previously monumented.

(12-Sec. 17) South 1/16 corner, Section 17. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 17) Established the position for the corner midway and on a straight line between Quarter corner E6 1320.73' east and the Center of Section 17 1320.73' west.

(12-Sec. 17) Established the position for the corner midway and on a straight line between Quarter corner D7 1351.23' south and the Center of Section 17 1351.23' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx30" I.pipe with 4" alum. MDNR cap.  
The monument leans slightly to the west due to a large rock. The center of the cap marks the corner position. Set measuring nail with MDNR tag in the side of:  
8" W.Birch S41°W 7.9' mrkd "E1/16 BT"  
10" W.Birch S28°E 17.9' do  
10" Maple N26°E 9.95' do  
13" Cedar N58°W 14.7' do

(12) Set 1"IDx30" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
14" W.Pine S61°W 12.6' mrkd "S1/16 BT"  
16" W.Pine S25°E 23.6' do  
14" W.Pine N42°W 18.85' do  
12" W.Pine N33°E 35.15' do

Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/15/2013

For the Michigan Department of Natural Resources, Forest Resources Division