## SURVEY & REMONUMENTATION

JAN 21 1999

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

**Mackinac County Remonumentation Corner** 

For corners in

Mackinac County Located in: Corner Code # T42N R01W 1. Public Land Survey T R Т R R T T R 2. Property Controlling R S T in Section S R 3. Miscellaneous Š Property in Sec.

RECEIVED & FILED DIANE FRANKOVICH MACHINAC COUNTY REGISTE OF DEEDS

DEC 3 1 1998

PM 7181911011111211213141516

> D F

32

3

7

8

9

10

11

12

1.3

Register of Deeds Stamp & File Number

G

L

24

36

4. Lot No.

, Recorded Plat

Private Claims

I, Nell E Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes James Mullett

6" Tamarack for 1/4 Post

1970 DNR Billy Buckler

12.8 ft

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING

33

HELD ON 12-11-98

MIC

nfil e HILL

Land Surveyo

S 01 W 30.7 ft 8" Cedar 7" Cedar Set 1" Pipe w/ 4" Alum Cap N 77 W 8" Cedar Liber 2, Page 310 3.0 ft East

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998 Fd DNR corner and 1 witness Accepted corner location

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is 1" pipe with 4" Alum DNR cap Corner is approx 100' East of old logging road

10" Cedar 6" Cedar

N 40 E N 20 E 11.00'

8" Cedar

S 70 E

16.28

8" Cedar

Due E

11.54 6.44'

Bearings are compass bearings, corrected for declination, all distances are to double-headed nail in the side of the witness object unless otherwise noted.

Signed by

Date

12-29-98

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983 REVISED OCT., 1995