

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N. R. 6W


Mackinac COUNTY

DESCRIPTION OF CORNER Section corner for sections 15-16-21-22

CORNER MONUMENT 1" iron pipe ; 1/2" X 16" iron bar (buried)

DATE MONUMENT PLACED AND WITNESSED 4-25-62

WITNESSES TO CORNER..... U.S. Geological Survey Monument N28°W, 53 links



CIRCLE CORNER REGISTERED

Fence Corner North 48 links

Fence Corner N39°E, 62 links

AND Road to South

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by D. Brotherton, Registered Land Surveyor, 1912.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 29, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler