

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Mackinac

(County)

Located In:

Corner Code ##

- | | | |
|------------------------------------|----------------|----|
| 1. Public Land Survey | T 42N R 7W | L4 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S 1 T 42N R 7W | 6 |
| | S 1 T 42N R 7W | 5 |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

L4 August 18, 1993
5 August 25, 1993
I, Stephan J. Szyszkowski, in a field survey on 6 September 01, 1993, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- (L4) Center of Section 12. Corner not established in the original survey. Found no subsequent record.
(6-Sec. 1) Northeast 1/16 corner, Section 1. Corner not established in the original survey. Found no subsequent record.
(5-Sec. 1) North 1/16 corner, Section 1. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (L4) Found no monumentation or evidence of use at the corner location. Established the corner at the intersection of a line connecting the East and West 1/4 corners with a line extending south from the North 1/4 corner of the section having a bearing equal to the mean of the bearings of the east and west sides of the section. The south 1/4 corner of the section was not established in the original survey. At the position for the corner, I placed a 1"x32" iron pipe capped with a 4" dia. cast aluminum MONR tablet.
(6-Sec. 1) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners, all monumented. At the position for the corner, I placed a 1"x32" iron pipe capped with a 4" dia. cast aluminum MONR tablet.
(5-Sec. 1) Found no monumentation at the corner position. Established the corner on a straight line between Center of Section 1322.48' south and 1/4 corner 1326.44' north, being 20 chains proportionate measure, north of the center based on the mean record distance of the north 1/2 miles on the east and west sides of the section. At the position for the corner, I placed a 1"x32" iron pipe capped with a 4" dia. cast aluminum MONR tablet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|---|--|---|
| (L4) Set a 1" pipe with a 4" MONR cap. Blazed, scribed, and set measuring nails in the following bearing trees:
6" Beech N30W 12.95' "1/4S BT"
10" Beech N76W 17.6' "1/4S BT"
12" Beech S12W 16.0' "1/4S BT"
10" Beech S68E 18.5' "1/4S BT"
Placed a 4" squared beech post adjacent. | (6) Set 1" pipe with 4" MONR cap. Blazed, scribed, and set measuring nails in the following bearing trees:
12" W. Pine N10W 30.95' "1/16S BT"
8" W. Pine N83W 19.15' "1/16S BT"
12" Spruce S30W 40.35' "1/16S BT"
5" J. Pine S05E 13.9' "1/16S BT"
Found a 1" pipe S20W, 73.05'
Placed a 3" squared W. Pine post adjacent. | (5) Set 1" pipe with a 4" MONR cap. Blazed, scribed, and set measuring nails in the following bearing trees:
3" Ironwood S18W 10.1' "1/16S BT"
3" Balsam S31W 5.0' "1/16S BT"
16" Maple S60W 31.8' "1/16S BT"
3" Balsam S85W 13.85' "1/16S BT"
Placed a location poster at a trail road approximately 112' west of the corner. |
|---|--|---|

Signed by Stephan J. Szyszkowski
LAND SURVEYOR

Surveyor's License No. 33986

Date 10-14-93