

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 NR. 10 West

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 6 - 7

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 2-24-58

13" white pine S 59° W 61½ links. Marked "S&BT"

8" cedar N 20° E 14 links. Marked "S&BT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. Re-established 1/4 corner by Single Proportionate measure between two
section corners. Found no evidence of original corner. Found old blazes in vicinity.
Corner lies in cedar swamp.

SURVEYORS SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR DATE 6-18-59