JAN 21 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For corners in RECEIVED & FILLU Corner Code # Mackinac County Located in: DIANE FRANKOWICH WAY MEETING OF DEEDS **T43N R1W** M-12 1. Public Land Survey A-12 (Same corner T43N R1E Chippewa County) DEC 3 0 1998 DMR AΜ T R 7181911012241411413141516 S Ţ R 2. Property Controlling S Т R in Section 3. Miscellaneous S R Register of Deeds Stamp & File Number Property in Sec. S ACCEPTED BY THE MACKINAG GOUNTY SURVEY PEER GROUP AS THE , Recorded Plat Lot No. R D Ε K L Α OFFICIAL CORNER UNDER PA. 5. Private Claims 345 OF 1990 AT A MEETING 2 11-50-08 HELD ON _ 6

I, Keith R. Waters, in a field survey on November 11, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-12 1/4 Corner Common to Section 36, T43N, R1W & Section 31, T43N, R1E

1840 - Original corner established by William A. Burt.

1991 - MDOT notes found iron with cap #33142 and witnessed prior to road construction.

1992 - LCRC, liber 7, page 354, Chippewa County corner records. Neil E. Hill, P.S. 27447, found a 1/2" iron with cap #33142 in a monument box undisturbed after road construction. Checks well with 1991 witnesses. Witnesses: Nail and MDOT tag in 4" Balsam fir, WEST 42.27'

Nail and MDOT tag in 8" Cedar, N60°W 55.06"

Punch top concrete right-of-way marker, N85°W 38.73'

Nail and MDOT tag in 4" Cedar, N75°E 76.05'

Nail and MDOT tag in Power pole (E34), S35°E 113.27'

1994 - LCRC, liber 8, page 310, Chippewa County corner records. Keith R. Waters, P.S. 33142. Found a 1/2" iron with cap #33142 in a monument box and all record witness objects as called for in 1992 LCRC.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Mackinac County Remonumentation Program. Found a 1/2" iron with cap #33142 in a monument box and all record witness objects as called for in 1992 and 1994 LCRC's.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a ½" iron with cap #33142 in a monument box at the corner location, which falls in Highway M-129. Witnesses:

Nail and plastic tag #33142 in 4" Balsam Fir, WEST 42.27' Nail and plastic tag #33142 in 10" Cedar, N60°W 55.06' Punch in top of concrete right-of-way marker, N85°W 38.73' Nail and MDOT tag in 4" Cedar, N75°E 76.05' Nail and MDOT tag in Power Pole (E34), S35°E 113.27'

Signed by ___

12-23-98

8

9

10

12

20

22

23

24

Surveyor's Michigan License No. 33142

SATE OF MICHIGAN

KEITH R. WATERS

PROFESSIONAL

SURVEYOR No. 33142 OFESSIONA)

¥