

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/2 Corner between Secs. 12-13

CORNER MONUMENT _____

DATE MONUMENT PLACED AND WITNESSED 6-8-68

WITNESSES TO CORNER..... 15" W. Birch (1/2 S NBT) S40°E 35.2'



8" Cedar (1/2 S NBT) S45°W 31.8'

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two sec. corners.
Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 10-8-68
REGISTERED LAND SURVEYOR