

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

3 Corners.

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		8-Sec.18, 11-Sec.18
2. PROPERTY CONTROLLING IN SECTION <u>18</u> , T. <u>43</u> N. _____ S. _____ R. <u>10</u> E. _____ W. _____		12-Sec.18
3. MISCELLANEOUS PROPERTY IN SECTION _____ , T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-31, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

8-Sec.18 West 1/15 Corner of Section 18.

11-Sec.18 South-West 1/16 Corner of Section 18.

12-Sec.18 South 1/16 Corner of Section 18.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8-Sec.18 Placed corner midway bet. 1/4 cor. to West and Center cor. to East.

11-Sec.18 Placed corner at intersection of lines quartering the quarter section.

12-Sec.18 Placed corner midway bet. South 1/4 corner and center corner of section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminum cap at all corners. Bearings:

8-Sec.18 5" Cedar, S66°W, 6.2' & 6" Cedar, N7°E, 14.8' & 6" Cedar, S72°E, 29.1'.
Corner lies 23' North of an E-W fence line.

11-Sec.18 10" S. Maple, N74°W, 25.3' & 5" S. Maple, N6°W, 48.9' & 7" S. Maple, S72°E, 22.0'
Scribed 4" Balsam, 1.0' West of corner.

12-Sec.18 12" Twin H. Maple, N29°W, 124.1' & Soft Maple clump, S66°W, 49.9' & Corner lies 1.9'
West and 8.9' North of an old fence corner.

SIGNED BY Billy D. Buckler DATE 10-9-80

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:


SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)



SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET