

1993

1993 Mackinac County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Mackinac
(County)

Located In:

Corner Code =#

1. Public Land Survey T 43N R 2W C-3
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

RECEIVED & FILED
CLARENCE DEEDS
MACKINAC COUNTY DEPT. OF DEEDS

OCT 28 1993
A/A P/M
7/6/91 10/11/91 11/14/91 12/15/91

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, David B. Guthrie, in a field survey on June 2, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845: Established by J.H. Mullett, G.L.O. Survey. Set wood post and referenced: 12" aspen - S60°W - 29 Links / 10" aspen - N65°E - 11 Links.

1960: Survey by Ray Walker (M.D.O.T.)

1987: Survey by Richard L. Hays of Nordlund & Assoc. for U.S. Forest Service.
1989

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found 2½" x 3' aluminum monument with a 3" aluminum cap stamped to identify the corner. Set in 1987 by Richard L. Hays, P.S. No. 25847 to replace a 1½" iron pipe previously found by Ray Walker (MDOT). Recorded by Richard L. Hays on January 8, 1990. (Book D, page 22). Plat of Survey Recorded as U.S. Gov't. Plat of Survey No. 14.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: N40°W - 85.92 feet - 10" Aspen
S46°E - 46.51 feet (R= 46.49') - 14" Spruce
S80°W - 40.60 feet (R= 40.54') - 8" Aspen
N47°E - 55.90 feet (R= 55.61') - 5" Aspen
The monument is a 2½"x3' aluminum monument with a 3" aluminum cap stamped to identify the corner.
(Tree references are blazed and tagged)



Signed by David B. Guthrie

Date 9/27/93

Surveyor's Michigan License No. 22435

D-0201