

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

3 Corners.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. _____ N. _____ E. _____ S. _____ R. _____ W. _____		8-Sec.25, 9-Sec.25
2. PROPERTY CONTROLL- 25 _____ T. 44 _____ N. _____ E. _____ ING IN SECTION _____ S. _____ R. _____ W. _____		10-Sec.25
3. MISCELLANEOUS _____ T. _____ N. _____ E. _____ PROPERTY IN SECTION _____ S. _____ R. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 9-2, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- 8-Sec.25 West 1/16 Corner of Section 25.
- 9-Sec.25 East 1/16 Corner of Section 25.
- 10-Sec.25 South 1/16 Corner on west side of Section 25.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 8-Sec.25 Placed corner midway bet. West 1/4 corner and center of Section 25.
- 9-Sec.25 Placed corner midway bet. East 1/4 Corner and center corner.
- 10-Sec.25 Placed corner midway bet. 1/4 Corner to North and Sec. Cor. to South.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminum cap at all three corners. Bearings are:

- 8-Sec.25 5" Cedar, S71°W, 24.1' & 5" Cedar, South, 17.8' & 7" W. Birch, S34°E, 4.3'.
- 9-Sec.25 8" Cedar, S72°W, 14.0' & 10" Tamarack, N38°E, 9.3'.
- 10-Sec.25 6" Spruce, S53°E, 13.5' & 8" Spruce, S18°E, 13.5'.

SIGNED BY

Billy D. Buckler
Billy D. Buckler

DATE 9-29-80

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

