STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

| | | Mackinac | COUNTY |
|--|-------------------------------|----------|--------|
| | | T AAN | R 9W |
| DESCRIPTION OF CORNER _ | Sec. Cer. cemon to Secs. 1-2- | 11-12 | |
| CORNER MONUMENT 1" pipe with 4" aluminum cap | | | |
| DATE MONUMENT PLACED AND WITNESSED #-16-68 | | | |
| WITNESSES TO CORNER | 5" seft maple (S11 NBT) S43"W | 59.31 | |
| N 1 | | | |
| | AND | | |
| CIRCLE CORNER REGISTERED | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by preportionate measure from cernersy $\frac{1}{2}$ mile north; one mile south and chainage to corner, one mile east as noted by Marcus Schaaf, F.L.S. who located the original cerner about 1934. Could not locate Schaaf's cerner so re-established as here noted.

Corner lies 330 east of pine plantation and 500 east of trail read.

SURVEYOR'S SEAL

SIGNED

Cilly D. Buckler
Billy D. Buckler

3-14-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing