

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 44N R 9W

DESCRIPTION OF CORNER 1/2 Cor. bet. Secs. 26-27

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-26-68

WITNESSES TO CORNER..... 15" W. Pine (1/2 S NBT) S70°E 56.4'



9" W. Pine (1/2 S NBT) S32°W 78.0'

AND \_\_\_\_\_

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as set by Marcus Schaaf, R.L.S. in 1934.

Found iron fence post in N-S fence line. No evidence of original cor.

Cor. lies 20' west of road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

3-14-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing