## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			Mackinac		COUNTY
	•	Τ.	44N	R _	9W
DESCRIPTION OF CORNER	Sec. Cor. common te Secs. 23-21	4-25	-26		
CORNER MONUMENT 1" pip	with 4" aluminum cap.		·- · · ·		<b>.</b>
DATE MONUMENT PLACED AND	WITNESSED 3-21-69				
WITNESSES TO CORNER	10" R. Pine (S 26 NBT) West	48.6	1		
N D	7" Tamarack (S24 NBT) N77°E	18.0	D1		
25	AND		<u>.</u> .	<del></del>	
CIRCLE CORNER REGISTE	RED				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by double proportionate measure. Found no evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler DAT

ATE 4-22-69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68