

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44-45 N.R. 10-11W


Mackinac Luce COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 6, 1, 36, 31

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 11/3/60 with J. Halbach, D.F.

WITNESSES TO CORNER....11" Hard Maple (S 31 NBT) N 30° E 50 Links



11" Y. Birch (S 36 NBT) N 67° W 101 Links

11" Y. Birch (S 1 NBT) S 30° W 73 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old Cedar Post at intersection of old township roads to south and east. Position fits well with corners in area. No evidence of original corner. Squared and scribed 6" hard Maple at Corner.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/23/61