

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970  
Mackinac Co. Three Corners

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY. T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		11, Sec. 16 4, Sec. 16 7, Sec. 16
2. PROPERTY CONTROL- ING IN SECTION 16, T. 44 N. _____ S. _____ R. 11 E. _____ W. _____		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. _____ S. _____ R. _____ E. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 8/21 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 11, Sec. 16 Placed SW 1/16 Corner at intersection of lines, quartering the South-West quarter section.
  - 4, Sec. 16 Placed NW 1/16 Corner at intersection of lines, quartering the North-West quarter section.
  - 7, Sec. 16 Placed North 1/16 Corner, on east side, Sec. 16, midway between NE Sec. Cor. and the East 1/4 Corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 11, Sec. 16 Buried 1 1/2" x 30" pipe on south edge of County road.  
Bearings are:  
8" Soft Maple N51°E 61.4' and 6" Soft Maple N33 1/2°W 44.2'
  - 4, Sec. 16 Placed 1" pipe with 4" aluminium cap at corner.  
New Bearings:  
7" Y. Birch S62°W 15.8' and 8" Soft Maple S53°E 52.1'
  - 7, Sec. 16 Placed 1" pipe with 4" aluminium cap at corner.  
New Bearings:  
6" Cedar N14°W 23.2' and 6" Cedar N33°E 19.8'

SIGNED BY: Billy D. Buckler DATE 9/13/72  
Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_