

APR 29 1996

COMMISSION

C0257457 LIBER:06779 PAGE:631 03:43P 10/03/1995
CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>MACOMB</u> (County)	Located in: Sterling Township	Corner Code #
1. Public Land Survey	T <u>2N</u> R <u>12E</u>	<u>C-6</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehouse, in a field survey on June 20 19 95,
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required
in the current manual of survey instructions of the United States Department of the interior, Bureau of
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,
found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-6	1817	G.L.O. Notes	Wampler	N/A	Set Post
	1972	L.C.R.C. L. 2346 P. 633	Patterson	#17631	1/2" Iron
	1976	Cert. Survey L. 2666 P. 586	Ankrom	#21265	1/2" Iron
	1976	Cert. Survey L. 2717 P. 311	Avey	#15396	N/A

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-6 Found a 1/2" rebar in a monument box in the center line of Ryan Road running N-S, 59.83' East of a plat monument on West
R/W. All witnesses of L.C.R.C. L. 2346 have been destroyed. Check witness Cert. Survey L. 2666 P. 586.

Cert. Survey L. 2666 P. 586
Plat Monument West 59.83'
Power pole S 50° W 32.65'
Power pole N 80° E 55.65'

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990 AT A MEETING HELD
ON 8/15/95
William E. Soderberg
WILLIAM E. SODERBERG, P.S., CHAIRMAN

Measure N 2626.96 to C-5 (Villager Sub. = 2626.92) (Mid Hampton Sub. #3 = 2626.51) (G.L.O. 2640.0)
Measure S 2634.57 to C-7 (G.L.O. 2640.0)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-6 I replaced the found 1/2" rebar with a 3/4" x 24" iron rod w/2" diameter aluminum cap stamped "Macomb County Monument
MI Act 345 #25854" in an existing monument box.

Nail and Macomb Co. Remon. Tag in S Face P. Pole Due West 50.84'
Nail and Macomb Co. Remon. Tag in NE Face P. Pole N 25° W 115.91'
Nail and Macomb Co. Remon. Tag in N Face P. Pole Due East 55.66'
SW Corner Square Catch Basin S 30° E 45.44'

The selected location is accepted by me and is generally accepted by professional surveyors
as the best available evidence of the position of the original corner.

Signed by Randy J. Kolehouse Date 9/4/95
Surveyor's Michigan License No. 25854

