C0863651 LIBER:08565 PAGE:890 09:45A 01/19/1999 CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Force	orners in		Fill	ng Requireme	nt of Act 74, Mich.	P.A. 1970						
	MACOMB (County)		Located in: City of Sterling Heights		Corner Code #							
1. F	Public Land	T R J-11 T R					1984 1 5 3999					
ir	T R roperty Controlling S T R Section S T R iscellaneous S T R					SECTION Register of Deeds Stamp & File Number						
	Property in S			·								
	. • 1	_										
4. L 5. F	.ot No Private Clain	, Red ns	corded Plat									
								* C	E F	9 +	TÌ	ŤĨ
I. Bruce Antcliff , in a field survey on September 3 19 98, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all In the same town and range, may be recorded							3 4 5 6 7 8	7 - 8	7 16 21 21 23 28 28 28	10 15 22 27		-1324
		s certificate.			mgo, may be reserve	.00	11		-	1	+	+
Α.	Description	on of original n	nonument and ac	cessories and/o	or subsequent resto	ration:	12	31 3:	33-	34	35	-36
J-11	1817 1978 1978 1979 1987 1996 1996	L.C.R.C. L. 69	966 P. 177 184 P. 574 L. 6329 P. 240	Wampler Menzel Patterson Fenn Stephens Fenn Fenn	N/A #7313 #17631 #23505 #29252 #23505 #23505	Post N/A P.K. Nail P.K. Nail P.K. Nail 1/2" Iron #2 N/A	21570 in	ı Mon. E	Вох			
В.	Description	on of corner ev	/idence found and	d/or method app	olied in restoring or	reestablishi	ing corn	er:				
 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-11 I found a capped iron #21570 in a monument box on the C/L of 15 Mile Road (conc.) running East and West Lawn Gardens and witnesses listed below. 										h checks	Maple	
	S 05° E 60 S 25° W 1 N 80° W 8	07.22' NW Cor 31.94' C/L Hydr	orner Post (m. 60. ner of Tower 2708	L.C.R.C. L. 6900 P. 881 N 45° E 93.62' PK nail/tag in SE face Util. pole (m. 93.67') S 34° W 62.23' PK nail/tag in util pole (m. 62.23') N 53° W 86.12' PK nail/tag in util pole (m. 86.23') S 75° E 194.27' PK Nail/tag in util pole (m. 194.29')								
	Measure West 2716.69' to I-11 (G.L.O. = 2702.70') (Cert. Survey L. 6329 P. 240 = 2716.0') (LCRC L.3184, P.574 = 2716.50) (locopelli Estates L115,P42 = 2716.69)											
	weasure b	asi 255/.40°	to K-11 (G.L.O. =	2/02.70")								
C.	Description	on of monume	nt for corner and	accessories est	ablished to perpetu	ate locating	the po	sition of	the cor	ner:		
J-11	•		on with a 3/4" x 24 disting monument to		diameter aluminum o	pap stamped	l "Macor	nb Cou	nty Monu	ment Mi		
	N 60 N 40 S 25 S 45 S 70 N 46 N 03 S 20	n E'ly Side of D.E. Po SE'ly Side of D.E. Po SE'ly Side of D.E. F P. Pole n NE'ly Side of Light	Pole CTUP AS THE OFFICIAL CORNER UNDER MIC DAN POLE FUELIC ACT 345 OF 1990 AT A MEETING HELD ON 10/27/94									
			accepted by me ar			-		į		BRU(ANTCL	E IFF	
Signe	ed by/	Suce	EARTH TECH	2	Date _	11-29	5-98		* \$ 2 2 \	SURVEY No 2582		10

866

Surveyor's Michigan License No. 25826

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 2871 REVISED MAY 14, 1975 REVISED JAN., 1983