SURVEY & REMONUMENTATION

APR 2 9 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

1993

Company of more and

		Filing R	equirement o	f Act 74, N	flich. P.A. 1970	Nakaut Substrate a compa	√ रे
arnı stee	ers in					REGISTER'S OFFI	CE
3166	(County)	Located In:	Cor	ner Code =	7	MANISTEE COUNTY	Y
1. Publi	ic Land Survey	21N 13 T R _ T R _ T R _)k-10		#93-302 AT MAY 12 199 Penny a. Pew	
	erty Controlling	TR S T R S T R				REGISTER OF DEE	DS
3. Misc	ellaneous erty in Sec.	S T R S T R			' Reg	gister of Deeds Stamp 8	& File Number
4. Lot N	No ,	Recorded Plat	and the specialists commences to recover the			A B C D E F 6	g н I J К L
						2	
						3	
Normar	n C. Caldwell		Septer	mber	92	4 - 7 - 8 - 9 - 9 -	101112
1.		, in a field survey on quirements of P.A. 74, Michig	p		19	5	
in lines 1 current m Managem above well Court of expressed NOTE:	and 2 above were anual of survey instent or by a decree or in conformance w. Law; established, d below: Not more than 4	in conformance with regulat ructions of the United States a Court of Law and/or that the ith the rules of the Michigan re-established, monuments corners, all in the same to	ions and rules the Department of II se corner points me Board of Land Sued, re-monument	nerefore as re the Interior, 8 nentioned in l nerveyors or by led, recover	equired in the ureau of Land ines 3, 4 and 5 va Decree of a ed. found as	7 8 -19 -20 -21 9 10 -30 -29 -28	
	on this certificate					12 31 32 33	34-0-35-36
A. Desc	cription of original	monument and accessor	ies and/or sub:	sequent res	toration:		
1-12		John Brink, 1839 (55.44') 11" Y. Pine		κ-10	\$8°₩ 48 lks. (John Brink, 1839 31.68*) P. Pine 38.94*) P. Pine	
		evidence found and/or mo 34 & 35, 1218-R134	ethod applied i	n restoring K-10		corner: 25 & 26, T21N-R13W	
I - 12		Eng. Co. on July & Aug.	1000	κ το		Eng. Co. in July &	ani 12 13 130
	fnd. a 1/4 post No pipe set	- Not U.S., Not used -	1707		August 1909 No U.S. Evidend No Pipe Set		9. V . V . V . V . V . V . V . V . V . V
	Nanistee County J.H, F S75°E 701Ks9" S68°E 841Ks.		1907			OF MICH	11 to 12 12 12 12 12 12 12 12 12 12 12 12 12
	R.L.S. #16938 d Calculated a po	Property Survey by Paque ated 7/74 - 4/79. Did no sition for cor. at a pnt. ine between sec. cor c	ot find cor. Tequal dist.		i de la companya de l	NORMAN G. CALDWELL LANG SURVEYOR 12018	
	Robert Griffin nothing. Presu	vice land cor. record car gear.hed for sor. in 1963 med this to be a lost cor	S & fnd. Ther.			ACTOR TO AND	The Control of the Co
C: Desc	ription of monume	nt for corner and accesso	ries establishe	ed to perpet	uate locating th	e position of ane corne	54: 4 7 8 c Q
1-12	1/4 cor., Sec. At midpt or Placed 2" D. Ir accepted as a c of the position N20°W 26.72' N50°E 7.40' Oue South 39.4 S81°W 37.73' N80°E 58.14'	34 & 35, T21N-R13W Inc Inc In Pipe w/brass cap and in Areful and faithful reest of the original corner. 8" W. Oak 10" W. Oak 4' 6" W. Oak	is	K-10	1/4 cor., Sec. At milpt. or Placed 2" D. Ir accepted as a co of the position N20°W 55.60' S85°W 30.56' S16°W 62.29' S31°E 39.96' N56°E 54.85' South 1.0'	25 & 26, I21N-R13N n line ron Pipe W/brass cap and careful and faithful red n of the original corner 8" W. Pine 6" W. Oak 24" W. Oak	d is 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Signed b	Charles 1		Fire.d.		pate //	UMN 73	, and the second section of the second sections of
Surveyor's Michigan License No. 12018 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 19, 19, 19, 19, 19, 19, 19, 19, 19, 19							