LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, re-monumented, recovered, found as expressed below:	L M
1. Public Land Survey T_2IN_R 13_W T_REGISTER OF DEEDS 2. Property Controlling S_T_R In section 3. Miscellaneous S_T_R Property in Sec. S_T_R 4. Lot No, Recorded Plat	L M
1. Public Land Survey T 21N R 13 W REGISTER OF DEEDS T R R Register of Deeds Stamp & File Number 2. Property Controlling S T R R Register of Deeds Stamp & File Number 3. Miscellaneous S T R R Register of Deeds Stamp & File Number 4. Lot No. Recorded Plat S Private Claims 1. Kenneth L Ross I and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, morrumented, re-monumented, recovered, found as expressed below:	13 24
REGISTER OF DEEDS T R 2. Property Controlling S T R in section S T R 3. Miscellaneous S T R Property in Sec. S T R 4. Lot No. Recorded Plat 5. Private Claims 1. Kenneth L Ross in a field survey on June 8 19.98 on the field survey on The current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	12 13
2. Property Controlling S T R in section S T R 3. Miscellaneous S T R Property In Sec. S T R 4. Lot No, Recorded Plat	12 13
2. Property Controlling STR in section STR 3. Miscellaneous STR Property in Sec. STR 4. Lot No, Recorded Plat	12 13
in section S. T. R. Property in Sec. S. T. R. 4. Lot No, Recorded Plat	12 13
4. Lot No, Recorded Plat	12 13 24
4. Lot No, Recorded Plat	12 13 24
4. Lot No, Recorded Plat	13 24
I. Kenneth L. Ross in a field survey on <u>June 8</u> 19.98. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, monumented, re-monumented, recovered, found as expressed below:	13 24
I. Kenneth L. Ross., in a field survey on <u>June 8</u> 19 98. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, monumented, re-monumented, recovered, found as expressed below:	13 24
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	- 24
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	
Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:	25
11 	1 1
MANNER. Next we are shown at a summary all the shown a series are designed where the proportion of the state	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	36
A. Description of original monument and accessories and/or subsequent restoration:	
M-03 Section Corner for Sections 1 & 12. T21N-R13W.	
1839, John Brink, G.L.O. 1959, George Blass, RLS # 5489 Set Wood Post Did extensive work to recover the	
#1 Maple 10" S 21 W 40 lks.(26.40') original GLO corner, found 3 white pine stps #2 White Oak 10" N 68 W 15 lks.(9.90') at a point faced by stumps, found remains	•
of very old wood stake, check creek calls 1908, Don Skeels, M.C.S. North and East, to confirm as original cor.	
monument not given, show 2640.00' to East 1/4 8-12 Set 6" by 5.0 long concrete monument, with #3 Yellow Pine Stp. 10" S 22 W 25.00' 3-1/2" Brass cap, stamped to identify the	
#4 Yellow Oak 6" N 35-30" W 26.00" corner. (Book "B", Page 320) #7 Existing "BT" W. Fine Stp. 24" due East	
1909, Fargo Eng. Co. 11.37' (blazed 4 marked) Found Stake (no U.S.) \$8 Existing "BT" W. Fine Stp. 30" N 11 W	
#5 Black Oak 6" M 80 W 89.5 lks(59.07') 27.10' (blazed 4 scribed "BT") #6 White Pine Stp. 10" H 15 W 52.5 lks.(34.65') #9 Existing "BT" W. Fine Stp. 24" 8 50 W	
(Book "A", Page 2) 22.90'(blazed) #10 White Oak 14" N 10 W 32.54'(sgr. BT 1)	
1973, Jack F. Erickson, RLS \$16929 \$11 White Oak 12" N 87 W 73.00' (scrb. BT 12) Found con. monument by Blass \$12 White Oak 10" 8 77 E 40.55' (scrb. BT 7)	
Used witness \$10, \$12 and \$13 (L. 1, Page 364) \$13 White Oak 12" 8 22 W 25.25' (sorb. BT 12) (liber 1 Page 428, Wexford Co.)	
1992, Norman Caldwell, RLS #12018 Found Con. Monument stamped RLS #5489	
#14 Pipe 3/4" RLS Cap #12018 8 57 % 120.74'	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
M-03 Section Corner for Sections 1 6 12 T21N-R13W. On June 8, 1998, I found 6" round concrete monument placed by Blass, monument is one foot	
above the ground and is 100 feet east of trail road, I found no evidence to dispute this location for the corner.	
Condition of record witnesses as follows are: \$1 Gone \$2 Gone \$3 Gone \$4 Gone \$5 Gone	
#6 Gone #7 Found stump #8 Found stump #9 Found stump #10 Found in good condition	
\$11 Found in good condition \$12 Found out(logged) \$13 Found in good condition \$14 found in good cond.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
I accepted Blass's 6" round concrete monument with a 3 1/2" brass cap, stamped to identify the corner as a substantial marker for the corner and is accepted as a careful and faithful perputifietion	
of the position of the original corner. Ext. "BT" 10 White Oek 16" N 10 W 32.54' (dock spk. in NE side of tree)	
Ext. "BT" 11 White Oak 14" N 87 W 73.00' (dock spk. in North side of tree)	<u>L</u>
New "BT" 4 Black Oak 18" N 24 E 18.34' (set 60d spk. in SE side of tree)	
Signed by J Jake Surveyor *	Ξ.
Surveyor's Michigan License No. 17634 FORM APPROVED BY MICHIGAN STATE BOARD OF AND SURVEYORS, AN	Ē
Corner $M - Z \ge 1$ ratified by the Manistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1990,	DL 20, 1071 AY 14, 1978
as amended, (being the State Survey and Remonument Act, MCL 54.261	EN 20, 1071 ENY 14, 1978 D.JAM., 1963 MARCH, 1963
on amortional footified and amore and and communitarity and these arms.	51. 20, 1071 FAY 14, 1978 D JAM., 1963 MARCH, 1963
et. seg.). Date of Peer Review: 1111 7 1908 Anthony m. Slowish	50. 20, 1971 50. 20, 1971 60 JAM, 1981 60 JAM, 1983 60 JAM, 1983