

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in
MANISTEE
(County)

Located In:

Corner Code #

1. Public Land Survey

T 21 N R 14 W

T 21 N R 13 W

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____, Recorded Plat _____.

5. Private Claims _____.

I, Sammy S. Barnett, in a field survey on August 22nd 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M - 7 Corner common to sections 18 & 19, T21N, R13W & sections 13 & 24 T21N, R14W

1837 GLO survey by John Brink, set post

1 Maple 10" S73 1/2W 35 lks (23.1')

2 W. Oak 14" N45W 48 lks (29.7';

1907 Survey by J.H. Millard, Mon. not given

3 Maple stub 10" S80E 22 lks (14.52')

4 W. P. snag 30" S48W 45 lks (29.7')

(Found "point and BT roots")

1963 Survey by R. A. Griffin, found remains of a rotted wood stake and the W. Pine witness used by J.H. Millard. Placed a 5" square concrete monument with a brass disk stamped to mark the corner.

5 Maple 6" N27E 40.90' dock spike in SE side

6 W. Oak 4" S20E 18.80' dock spike in NE side

7 W. Pine 15" S74W 101.65' dock spike in NW side

8 R. Oak 6" N47W 43.65' dock spike in NE side

9 Cedar post S. 1.5'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 7 Corner common to sections 18 & 19, T21N, R13W & sections 13 & 24 T21N, R14W

On August 22nd 1997, I found the 5" square concrete monument set by R. A. Griffin

Condition of the witnesses are as follows,

1 Gone # 2 Gone # 3 Gone # 4 Gone # 5 Found (6") # 6 Found (4") # 7 Found (20") # 8 Found (16") # 9 Found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 6 Corner common to section 18 T21N R16W & section 13 T21N R15W

On August 22nd 1997, I accepted the found 5" square concrete monument as a careful and faithful perpetuation of the original corner, and took the following witnesses.

10 Maple 7" N27E 40.92' (#5) dock spike in SE side

11 W. Oak 4" S20E 18.83' (#6) dock spike in NE side

12 W. Pine 20" S74W 101.67' (#7) dock spike in NW side

13 R. Oak 16" N47W 43.50' (#8) dock spike in NE side

14 7"x7" post S. 1.5' (#9)

USFS red line running East
Two track trail 130'+- East

Corner M-07

ratified by the Manistee County Peer Group
according to the county plan adopted pursuant to P.A. 345 of 1971
as amended, (being the State Survey and Remonument Act, MCL 561.51
et. seq.) . Date of Peer Review: OCT 7 1997

Signed by

Sammy S. Barnett

Date 10-17-97

Surveyor's Michigan License No. P S # 16923

REGISTER'S OFFICE
MANISTEE COUNTY

97-398 Oct 31:45pm
OCT 24 1997

Deborah Six

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

