F. .

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

	Lining Medi	menicit of Act 14, mon. 1 .A.	REGISTER'S OFFICE
For corners in MANISTEE	Located In:	Corner Code #	MANISTEE COUNTY
(County)	Located III.		99-170 at 3:05pm MAY 20 1999
1. Public Land Survey	T 21N R 17W T R	E-13 mc	Stebonoh Six REGISTER OF DEEDS
	TR	#011	REGISTER OF DEEDS
2. Property Controlling S	TR T R		
in Section S_			Desirter of Deade Stomp & Eile Number
3. Miscellaneous S_ Property in Sec. S_	TR TR		Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat		— _ABCDEFGHIJKLM
5. Private Claims			
			2 6 5 4 3 2 1
I, Richard L. Hays	, in a field surv	rey on APRIL Z8TH 19 99,	4 - 7891611 - 12 -
in lines 1 and 2 above were in o	conformance with regulations a	A. of 1970, the corner points mentioned and rules therefore as required in the	5
current manual of survey instructi	ons of the United States Depart	rtment of the Interior, Bureau of Land ner points mentioned in lines 3, 4 and 5	6 18 17 16 15 14 13
above were in conformance with	the rules of the Michigan Board	of Land Surveyors or by a Decree of a nonumented, recovered, found as	8 19 20 21 22 23 24
expressed below:	-established, mondificiti, 10-11	ionalitica, reservica, resire as	9
NOTE: Not more than 4 co	rners, all in the same tow	n and range, may be recorded	10 30 29 28 27 26 25
on this certificate.			12 31 32 33 34 35 36
A Description of original n	nonument and accessories	and/or subsequent restoration: East margin of Lake Michigan o	on 13
the South Line Section 32	, T21N-R17W.		_
1839, John Brink, G.L.O. Set Wood Post #1 Hemlock 16" S 42 #2 Hemlock 14" N 46 Note set corner at Section for 32 and	2 E 20 lks.(13.20') 3-30' E 53 lks.(34.98') t 11 chs. (726.00') from	corner for SE corner of witness, Boo the Bluff L:	the Township line by finding the NW Section 5 T20N-R17W (Axle Shaft) & the f Section 33, T21N-R17W, (found Millard's book A page 82. Then pushed line West to time of Lake Michigan, set concrete mon.
1967, Thomas J. Vallence Establish the Sout as shown in the P: was set.	ourt P.E. 9292 th line of Section 32 & Lat of Lake & Land Sub.	Conc. monument Set 4' bearis #3 Beech	an M.S.H.D. " sq. Pine Post from remains of original ng tree. 10" N 60 E 25.80' Birch 10" S 10 E 40.40'
B. Description of corner ev E-13 mc, Witness Corner in R17W.	idence found and/or metho	d applied in restoring or reestablishi he <u>Bast margin</u> of La <u>ke Michiga</u>	ng corner: n on the South Line Section 32, T21N-
monument to used as a wit	tness to meander corner ander corner by pushing ents on the Township Li	. Due to Bluff erosion, monume	
CONDITION OF RECORD WITH	added film for rotations,	5E-13	ratified by the Manistee County Peer Grou
C. Description of monume	ent for corner and accessori	according to the coas amended, (being et. seq.). Date of P	the State Survey and Remonument Act, MCL 54.26 reer Review:  **How many and Remonument Act, MCL 54.26 reer Review:  **How many and the position of the corner:
I Set a Standar ft., West from the Secti	d Manistee County Monum on corner (E-13) and to	ent, Stamped Witness corner to ook four new witnesses and is a	the Meander Corner a distance of 453.97 ccepted as a careful and faithful re-
establishment of the pos	ition of the original c	orner.	•
Maple 5" N 28 W 4.	65' (set 60d spike in N 64' (set 60d spike in N 23' (set 60d spike in S 42.07' (set 60d spike to E-13 of 453.97 ft.	R side of tree) W side of tree) Se in NW side of tree)	
Signed by	and Hays	RICHARD  L HAYS  LAND	5/ME/99
Surveyor's Michigan License	: No. <u>25847</u>	SURVEYOR Ni) NO. 3	ORDAN PROVIDED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 187
1975		25847 MINISTED LAND	ORNAPPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JUNE 26, 197 REVISED JAN., 1983