

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	22N N. 13W S., R. E. W.	C8(i)
2. PROPERTY CONTROLLING IN SECTION _____	N. S., R. E. W.	<i>Other #1</i>
3. MISCELLANEOUS PROPERTY IN SECTION _____	N. S., R. E. W.	<i>Should be #4</i>
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER'S OFFICE
MANISTEE COUNTY
95-237 AT 10:58
JUN 22 1995
Barney A. Peters
REGISTER OF DEEDS

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Patrick R. Leemon do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on April 17 1995, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Indian Reserve Corner common to Sections 19 and 20 of T22N R13W

1837 GLO survey of the Manistee Indian Reservation by John Brink No monument was set
1839 GLO survey by John Brink Set a wood post at the intersection with the reservation boundary,
(1) W.Pine 18 N25E 28 links, (2) Beech 8 N17W 80 links
1847 GLO survey within the Manistee Indian Reservation by Orange Risdon Intersected the reservation boundary
1900 survey by Jos. Millard County Surveyor Found the stump of a GLO BT and point of stake,
(3) W.Pine 24 S86E 26.5 links, (4) W.Pine Stp. 36 N59W 43 links
1935 search by Passmore U.S.F.S. Found a W.Oak stake, (5) W.Pine 24 S49E 33.5 links,
(6) W.Pine 30 N76W 53.2 links, (7) R.Oak 24 S30W 40 links
1936 survey by Manistee Co. Rd. Comm. Found rotted wood stake at corner, (8) B.Oak 20 South 25'-7"
- continued on back -

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I found the 6"x36" monument buried 6" below the surface and in good condition. Witnesses 1 through 8 are gone. Witnesses 9 and 11 through 13 are in good condition. Witness 10 is a stump. The corner is 9 feet north of the centerline of a road to the east, and 41 feet west of the centerline of a road to the south, and 4 feet east of the centerline of a road to the north, and in the north track of a driveway to the west. Liber 73 Page 46 and Liber 77 Page 35 by Griffin documents the history of this corner. I accept this monument as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Indian Reserve Corner common to Sections 19 and 20 of T22N R13W

I left the 6"x36" concrete monument w/ brass cap as I found it.
(9) R.Oak 29 N52E 58.80 feet
(11) R.Maple 21 N25W 76.68 feet
(12) R.Maple 7 N75W 54.81 feet
(13) R.Oak 7 N16W 65.34 feet
Iron Gate Pipe 4 S69W 44.13 feet
W.Oak 5 S12E 54.74 feet

Corner C-081 ratified by the Manistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1930, as amended, (being the State Survey and Monument Act, MCL 54.26; et seq.). Date of Peer Review: MAY 2 1995

Anthony M. Stambler

SIGNED BY *Patrick R. Leemon* DATE May 30, 1995

SURVEYOR'S MICHIGAN REGISTRATION NO. 31595

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____



CORNER NUMBERING CODE DIAGRAMS FOR IDENTIFYING LAND CORNER RECORDATIONS AND INDEXING

FOR PUBLIC LAND SURVEY CORNERS IN THE
T. _____, R. _____ (MENTIONED OVER)

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Apply letter prefix for corner points encircled above for identifying corner recordation numbers over.

REGISTER'S OFFICE
MANISTEE COUNTY

#95-139 AT 10:58 A.M.

JUN 22 1995

Penny A. Papp
REGISTER OF DEEDS

FOR PROPERTY CONTROLLING AND MISC.
PROPERTY CORNERS WITHIN THE SECTION
(MENTIONED OVER AND EXCLUDE LOT CORNER)

	1		2	
3	4	5	6	7
	8		9	
10	11	12	13	14
	15		16	

1. Above coded numbers are positioned on 1/16 fractional lines of the section.
2. Township corner code numbers shall be applied to corners of above typical section not numbered.
3. Miscellaneous property corners within a section, located at points other than numbered above, shall be referenced to at least two of above corner code numbers.
4. Private claim corners to be tied to rectangular land corners if possible - sketch required below.

EXPLANATORY SKETCH IF NECESSARY -- BELOW

- Part A continued -

1973 survey by Robert A. Griffin #13584 Found the rotted wood stake and witnesses 4 and 8. Set a 6"x36" concrete monument w/brass cap 6" below the surface, (9) R.Oak 20 N48E 58.75 feet, (10) R.Maple 6 S46W 46.05 feet, (11) R.Maple 16 N25W 76.75 feet
1977 survey by Robert A. Griffin #13584 Took additional witnesses, (12) R.Maple 4 N77W 54.85 feet, (13) R.Oak 3 N20W 65.30 feet

1989 survey by Ken Ross #17634 Found and used the monument by Griffin. No new witnesses taken.

1991 survey by Robert Mitchell #28417 Found and used the monument by Griffin. No new witnesses taken.