REN

WAY 0 3 2000

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

<b></b>		•	SECTION	
	corners in		REGISTER'S OFFICE	
M	anistee Located In:	Corner Code #	MANISTEE COUNTY 97-335at4!45pm	
1. P	ublic Land Survey T_22N R_15	W <u>M-13 SE Sec. 36</u>	SEP 2 9 1999	
• • •	T <u>22N</u> R <u>1</u> 4	W (A-13) V	Belona Lir	
٠	T <u>21N</u> R <u>14</u> T <u>21N</u> R <u>1</u> 5		REGISTER OF DEEDS	
	roperty Controlling S TR Section S TR			
3. M	iscellaneous S TR_			
, <b>P</b> i	roperty in SecS TR_	· · · · · · · · · · · · · · · · · · ·	Register of Deeds Stamp & File Number	
4. Lot No, Recorded Plat				
5. P	rivate Claims		2 6 5 7 3 7 2 7	
		•	3	
I B	ruce J. Jenema , in a field su	invey on August 31 19 99 do	4 - 7 - 3 - 9 - 10 - 11 - 12 - 13 - 15 - 15 - 15 - 15 - 15 - 15 - 15	
hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current				
mani	manual of survey instructions of the United States Department of the Interior, Bureau of Land  Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  Court of Law; established, reestablished, monumented, recovered, found as expressed below:				
Cour	t of Law; established, feestablished, monumented, fed	overed, tound as expressed below:	9	
		<u>.</u>	10 -30 -29 -28 -27 -26 -25	
A.	Description of original monument and access	sories and/or	12 -31 -32 -33 -34 -35 -36	
	subsequent restoration:		BRUCE J. 2	
	1837 J. Brink, D.S., G.L.O. 1907 J.H. Millard			
Set post Recorded C.S. Book A. pgs 38, 131 & 118  1.) Beech 13" N84°E 7 lks (7.66') No U.S. Witnesses JENE			JENEMA	
	2.) Beech 11" N83 1/2°W 25 lks (16.50')  3.) W. Pine Stump 18" N 1/ 1/2°E 18 lks (11.88') 4.) W. Pine Stump 16" S541/2°E 82 lks (54.12')			
	,	5.) Y. Pine stump 10" N77°W 24 lks (1914 Fargo No Government witnesses	15.84') 25850 25850 CMALLAND	
	1959 Charles Dodt	6.) Y. Pine stump 10" N30°W 24 1/2 lks		
	Unrecorded survey Found Iron pipe	7.) W. Pine stump 10" S54 1/2°E 82 lks	S 134.12.1	
	8.) Oak 20" S5°W 64' 9.) Oak 16" N20°E (Distance illegible)		ratified by the Manistee County Peal adopted pursuant to P.A. 345 of Survey and Remonument Act. Mol.	
	1972 R.H. Kraft	1980 G.A. Fauser Consumers Power Co	Sat 3	
	Unrecorded survey Job. No. 220-71	Recorded Liber 1 of surveys page 809	e Manistre Course to P. Remonument	
	Found 1" pipe 10.) 7" Tw. Maple NE 66.59"	Found pipe with brass cap 12.) 17" Oak S9°W 52.14'	the Maris	
	11.) 9" W. Pine SE 66.93' 12.) 16" W. Oak SSW 52.10'	13.) 7" Pine S18"E 60.75' found 14.) 8" Pine S40"W 56.00'	y the	
	•	15.) 12" Oak S43°E 79.17' USFS ID South 33.86'	atified by adopted furney an	
	1990 Ken L. Ross	00.01.5000.00	adop Survey	
	Recorded Liber 2 of surveys page 176 Found U.S.F.S. Concrete monument	•	r plan State State	
B.				
	On Sept. 3, 1999, I found a standard US Forest Service concrete monument and brass cap.  No conflicting evidence of other corners existing.			
	Witnesses 1) 2) 3) 4) 5) 6) 7) 8) 9) 10) 14) are extinct			
	On Sept. 3, 1999, I found a standard US Forest Service concrete monument and brass cap.  No conflicting evidence of other corners existing.  Witnesses 1.), 2.), 3.), 4.), 5.), 6.), 7.), 8.), 9.), 10.), 14.) are extinct  Witness # 11.) & 15.) no marks on tree  Witness # 12 stump in poor condition Fd 60-D E. Side  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
Witness # 12 stump in poor condition Fd 60-D E. Side  C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
On Sept 3,1999, I found a 6" round concrete monument with a 3" brass cap stamped to identify the corner as a substantial marker for the				
	comer and is also accepted as a careful and faithful reestablishment of the position of the original corner and witnessed by: 13.) 12" W. Pine S18°E 60.77' Fd. 80-D spike E. Side 16.) 8" W. Pine N60°E 65.45' Set 60-D spike W. side			
	17.) 4" concrete monument North 33.06' Ross ID cap 18.) 12" W. Pine S05°E Set 60-D E. side 19.) 18" W. Pine S50°E 58.35' Set 60-D E. side 20.) USFS ID post South 33.86' #16 nail E. side			
<b>.</b>	2 11	·	9-16-99	
	ned by Such fanon a veyor's Michigan License No. 25850	Date	, 10-1	