| | LAND COR | NER RECORDATION CERT | TEICATE | 1993 |
|--|--|---|--|---|
| • 1 | | irement of Act 74, Mich. P | | IÍ CO I CORT |
| For corners in | , <u></u> | | COMIN | IISSION |
| Manistee (County) | Located In: | Corner Code ## | n | |
| Public Land Survey | T R T R T 720 R 1500 | (M-8) T22N | REGISTER'S CONTROL FEB 2 | |
| 2. Property Controlling | S 19 T 22N R 14W | | No. 93-34) AC | 4:00 AM |
| in Section | S | 3 | | |
| Miscellaneous Property in Sec. | S T R S T R | | Register of Deeds | Stamp & File Number |
| | | | | |
| 4. Lot No, F | Recorded Plat | <u> </u> | A B C D | EFGHIJKL |
| 5. Private Claims | · · · · · · · · · · · · · · · · · · · | | 2 6 5 | |
| | | | 3 | |
| Dehomt P. Witchel | 1 And | vot 01 | , ⁴├─ ╎ ─┼─╽─ | 4-9-10-11-11-11 |
| do horsely certify that under the | † in a field survey onAUS | ust 19 92 A. of 1970, the corner points men | tioned IIII | ! |
| in lines 1 and 2 above were i | n conformance with regulations | and rules therefore as required | in the | 15-1-14-1-1 |
| current manual of survey instr Management or by a decree of | ructions of the United States Dep a Court of Law and/or that the co | partment of the Interior, Bureau o Inner points mentioned in lines 3, 4 | Lance T | 31 32 33 3 |
| above were in conformance w | ith the rules of the Michigan Boa | rd of Land Surveyors or by a Decr | ee of a | |
| Court of Law; established, expressed below: | re-established, monumented, | re-monumented, recovered, fou | 10 30 29 | 28 27 26 2 |
| NOTE: Not more than 4 of | corners, all in the same towr | and range, may be recorded | 11 | |
| on this certificate | • | | 12 31 32 | 35-1-3 |
| A. Description of original | monument and accessories | and/or subsequent restoration | 13 <u> </u> | |
| established duri | ng the original U.S. | West line of Section Survey conducted by sablished this corner. | J. Brink in 1839. | rner was not . In 1900 J. |
| · | | od applied in restoring or rees | | |
| Millard's witness Surveyor Records | ses of 1900 as reco | West line of Section orded in Book "B" possible galvanized pipe with corners. | . 54-55 of the Mar | nistee County |
| | | | • | So to B |
| • | | | | Z . 65 |
| • | | | | 0,47 |
| | • | | | * 010 |
| , | | | | P. P. |
| | | | ٠, | od Sint |
| | | | anning the annition of th | atified Ursuan P.A. |
| C. Description of monumers | ent for corner and accessoric | es established to perpetuate l Line of Section 19; | ocating the position of the | acounter. |
| Set a 2" x 30" ga | lv. pipe w/ 3" brass | | | <u> </u> |
| flush with the gr | cound. | | 101 10 mm | d p a |
| | th - Wk Corner Sec. | | The state of the s | o de g |
| | 6°E - 6" Black Ash - 8°E - 7" Black Ash - | | ROBERT ROBERT | A to State of the |
| | 6°W - 13" Black Ash - | | LAND | am Date |
| S51 | "W - 6" Black Ash - | 34.29' | SUBVEYOR | i # #2 ₹₹ |
| Sou | th - carsonite post | - 1.01 | | 100 |
| | Q-CHOO | 10 | 0 | Corner County F 1915, as amended. |
| Signed by | 210 11030 | Date | | |
| Surveyor's Michigan Licen | se No | | FORM APPROVED BY MICHIGAN STATE | BOARD OF LAND SURVEYORS, JAN. 28, |