

# SURVEY & REMONUMENTATION

JUN 09 2000

JUN 6 2 38 PM '00

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MANISTEE

(County)

Located In:

Corner Code #

REGISTER'S OFFICE  
MANISTEE COUNTY

1. Public Land Survey

T 22 N R 14 W

M-81

T R

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

4. Lot No.

Recorded Plat

5. Private Claims

I, Sammy S. Barnett, in a field survey on June 10th 19 99, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M - 81 Indian reserve corner South of the East one-quarter corner of section 24, T22N, R14W

1837 GLO survey by John Brink

North on E. side sec. 24

39.50 crop line of 70,000 acre reserve

40.00 set 1/4 sec. post

1900 survey by J.H. Millard Book B page 48

found point of stake & GLO witnesses for 1/4 corner,

set post on Indian reserve line 50 lks

South of 1/4 corner.

# 1 W. Pine 22" N86E 13 1/2 lks (8.91')

# 2 W. Pine 20" S54W 65 1/2 lks (43.23')

1977 survey by R. Griffin, found rotted wood post and wit. by

Millard, set a 5" sq. x 60" con. mon. with brass cap.

# 3 R. Oak 7" S55E 24.27'

# 4 W. Oak 6" S30W 45.21'

# 5 4" sq. x 7' post South 1.8'

# 6 5" sq x 60" con. mon (E 1/4 cor) N 33.00'

1983 survey by A. Slawinski, fd. con. mon.

# 7 Poplar 5" S55E 24.27'

# 8 Oak 3" S30W 45.21'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 81 Indian reserve corner South of the East one-quarter corner of section 24, T22N, R14W

On June 10th 1999 I found the 5" sq con. mon set by R. Griffin, the condition of the witnesses are as follows,

Gone 1 & 2, found in good condition 3, 4, 5, & 6 did not check 7 & 8

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 81 Indian reserve corner South of the East one-quarter corner of section 24, T22N, R14W

On June 10th 1999 I accepted the found 5" sq. con. mon. as a substantial marker and this monument was accepted as the best available evidence of the position of the corner., and took the following witnesses.

# 3 R. Oak 8" S55E 24.27' fd. 90d spike in N. side

# 4 W. Oak 7" S30W 45.21' fd 90d spike in NW side

# 5 4" sq post S. 1.8 ft. no nail

# 6 5" sq con. mon. with brass cap N. 33.00', East 1/4 corner section 24

# 9 R. Oak 8" East 4.28' set 60d spike

Corner M - 281

ratified by the Manistee County Peer Group

according to the county plan adopted pursuant to P.A. 345 of 1990,

as amended, (being the State Survey and Remonument Act, MCL 54.261

et. seq.). Date of Peer Review: Anthony M. Slawinski

AUG 03 1999

Signed by

Sammy S. Barnett

Date

8/1/99

Surveyor's Michigan License No.

P S # 16923

