

DEC 29 1998

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MASON  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 19N R 16W

D-3

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No.

Recorded Plat

5. Private Claims

I, Kenneth L. Ross, in a field survey on June 22 1998,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law, established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-3 1/4 Corner for Sections 5 and 8, T19N-R16W

1838, Sylvester Sibley, G.L.O.

Set Wood Post

#1 Beech 14" S 41 W 18 lks. (11.88')

#2 Beech 6" N 41 E 6 lks. (3.96')

1899, R. O. Towns, Mason Co. Surveyor

Found Gov't witness tree #2, only distance

given is to the South 1/4 cor. Sec 8, at 80.61 chs.

(5320.26'). Monument not given.

(book 2 page 15)

1989, Gordon Bonney, RLS #12016

Set a 1/2" Re-Rod with RLS cap at a single pro-rate,  
between controlling corners. (liber 3 page 3)

#3 Wild Cherry 6" S 05 E 46.39'

#4 Wild Cherry 8" S 34 W 25.66'

#5 wild Cherry 6" N 35 W 48.25'

1995, Kenneth Ross, RLS #17634

Found and accepted 1/2" RE-Rod by Bonney

#6 Wild Cherry 4" N 50 W 28.08'

#7 Maple 4" S 46 E 28.08'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-3 1/4 Corner for Sections 5 and 8, T19N-R16W

On June 22, 1998, I found 1/2" Re-Rod set by Bonney in the center-line of Beyer Road.  
I found no evidence to dispute this location for the corner.

Condition of record witnesses are as follows; #1 Gone #2 Gone #3 Found in good condition

#4 Found in good condition #5 Found in good condition #6 Found in good condition

#7 Found in good condition

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-3 1/4 Corner for Sections 5 and 8, T19N-R16W

I replaced 1/2" Re-Rod by Bonney, in the exact location with a Harrison cast iron monument,  
stamped MASON COUNTY MONUMENT, I placed the monument 0.5 feet below road surface, and this corner is accepted  
as a careful and faithful re-establishment of the position of the original corner.

Ext. "BT" #3 Wild Cherry 4" S 05 E 46.40' (16p nail in West side of tree)

Ext. "BT" #4 Wild Cherry 9" S 34 W 25.66' (60d spike in SE side of tree)

Ext. "BT" #5 Wild Cherry 6" N 50 W 28.08' (60d spike in NE side of tree)

Ext. "BT" #7 Maple 5" S 46 E 28.08' (60d spike in SW side of tree)

Signed by

Date

Surveyor's Michigan License No. 17634

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1978

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993

Peer Group Reviewed

Date

LIBER -- 4 PAGE 220