

SURVEY &
REMONUMENTATION

MAR 16 1998

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION

Mason
(County)

Located In: Corner Code #

1. Public Land Survey T 20N R 16W B-13
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. Recorded Plat
5. Private Claims

I, Richard L. Hays, in a field survey on April 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-13 SOUTH QUARTER CORNER OF SECTION 31, T20N-R16W

1839: G.L.O Post

12" Beech N-47°-E 18 lks (1)
7" Hemlock N-49°-W 35 lks (2)

1891: JW Griswold
Deputy County Survey
No Witnesses:

1983: Lawrence Slater RLS #7439

Found Lode Stone with chiseled "X" on top
13" Stump North 26.91' (3)
Fence Post N-02°-W 86.40' (4)
7/8" Iron Rod S-87°-20'-09"-E 14.53' (5)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-13 SOUTH QUARTER CORNER OF SECTION 31, T20N-R16W

August 1997: Found Lode Stone with chiseled "X" on top.

Condition of the Witnesses are as follows:

12" Beech N-47°-E 18 lks (1) (GONE)
7" Hemlock N-49°-W 35 lks (2) (GONE)
13" Stump North 26.91' (3) (GONE)
Fence Post N-02°-W 86.40' (4) (Could Not Find)
7/8" Iron Rod S-87°-20'-09"-E 14.53' (5) (FOUND)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-13 SOUTH QUARTER CORNER OF SECTION 31, T20N-R16W

AUGUST 1997: Accepted Lode Stone as the Monument and accepted it as the best available evidence of the position
of the Original Corner.

1/2" Re-Rod N-03°-E 12.94'
1/2" Re-Rod N-54°-E 20.09'
1/2" Re-Rod S-40°-E 22.22'
1/2" Re-Rod South 16.95'
Closing Corner East 25.01
SW Corner West 2,511.40
SE Corner East 2,642.09

FILED

AT 4:01 O'CLOCK P M

NOV 20 1997

MARY GOLDEN KOLASKI
MASON COUNTY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

Signed by Richard Hays Date 11/6/97

Surveyor's Michigan License No. 25847

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

Peer Group Reviewed
and Approved
Date: Nov 2, 1997
Kenneth L. Hays
Mason County Surveyor