

SURVEY & REMONUMENTATION

MAR 16 1998

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **SECTION**
MASON
(County)

Located In:

Corner Code #

1. Public Land Survey

T 20N R 16W

J-13

2. Property Controlling in Section

S T R

3. Miscellaneous Property in Sec.

S T R

4. Lot No. Recorded Plat

5. Private Claims

I, Kenneth L. Ross, in a field survey on October 24, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
J-13 South 1/4 Corner for Section 35, T20N-R16W

1837, Mullett & Brookfield, G.L.O. Boundary survey
Set Wood Post

#1 Beech 8" N 63° E 30 lks. (19.80 ft.)
#2 Beech 10" N 73° W 21 lks. (13.86 ft.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
J-13 South 1/4 Corner for Section 35, T20N-R16W

On October, 24, 1997, I Ken Ross and Kevin Pritchard (survey tech.), searched for existing corner or evidence of a corner. We established the location of this corner by single proportional measurement between controlling corners 1-13, and K-13, on a straight line between J-1 and 1-1 of T19N-R16W. Corner is 6.57 feet west of J-1, T19N-R16W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
J-13 South 1/4 Corner for Section 35, T20N-R16W

Set a standard Mason County Monument, (5/8" re-rod, 24" long, with a 2 1/2" aluminum cap, stamped to identify the corner. Corner not set by government survey, this location is accepted as a careful and faithful establishment of the accepted location for this corner.

Maple 5" S 48° W 6.15 ft. (set 60d spike in SE side of tree)
Beech 16" N 68° W 33.40 ft. (set 60d spike in NE side of tree)
Red Oak 30" N 42° E 19.22 ft. (set 60d spike in NE side of tree)
Iron Pipe 1" North 12.00 ft. Top center, iron set 36" above ground
Closing corner for Section 2, T19N-R16W East 6.57 feet



Peer G. ...
and
Date: Nov. 5, 1997
Kenneth L. Ross
Mason County Surveyor

Signed by

Date

Surveyor's Michigan License No. 17634

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971

FILED

4 PAGE 117