

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MIDLAND
(County)

Located In:

Corner Code #

1. Public Land Survey

T 13N R 2W

G-9

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

219

STATE OF MICHIGAN
MIDLAND COUNTY
FILED

19 JUL 95 10:53 A.M.

BEVERLY J THAYER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, PAUL B. LAPHAM, in a field survey on MAY, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:
G-9 CORNER COMMON TO SECTIONS 22, 21, 28 & 27

1852 AUSTIN BURT, OLD COR., Y. BIRCH 12" S61°E 33 LKS., ASPEN 14" N35°W, 20 LKS.

1899 COUNTY SURVEY RECORDS. SURVEY OF SECTION 21

4-12-73 ALVA COURTRIGHT, FOUND NAIL IN RD. SET 5/8"x18" ROD, L.C.R.C.

4-8-82 RUDELL, FOUND 3/4" PIPE (132) 3-552

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dosier file; which was presented
to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-9 CORNER COMMON TO SECTIONS 22, 21, 28 & 27

Found 3/4" X 20" Pipe. Replaced with 5/8" X 18" Re-rod and Set Mon. Box per surveys by Courtright & Ruddell.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Corner, G-9 was approved for remonumentation at a Peer Review Committee Meeting on 6-6, 1995.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9 CORNER COMMON TO SECTIONS 22, 21, 28 & 27

Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box.
Accepted as best available evidence of the accepted position of the corner.

N48°W 62.47' - N&T IN POWER POLE (NEW)
S47°W 58.83' - N&T IN POWER POLE
S33°E 66.61' - N&T IN STUD POLE
N42°E 56.45' - N&T IN POWER POLE



Signed by

Paul B. Lapham

Date

6-12-95

Surveyor's Michigan License No.

9433