SURVEY & **REMONUMENTATION**

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

OCT 0 3 1996

REMON. COR. M-1, MIDLAND TWPOOR IN A SUNDEN LAND CORNER RECORDATION CERTIFICATE

كالاتك

For corners in

Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

STATE OF MICHIGAN HIDLAND COUNTY

Midland

(County)

1. Public Land Survey

2. Property Controlling in Section

3. Miscellaneous Property in Sec. Located in:

T

T 14N R 2E TISH R DE R

R Ţ R R R REMONUMENTATION & FILED

22 AUG 96 8:07 A.M.

BEVERLY J THAYER REGISTER OF DEEDS


Register of Deeds Stamp & File Number

, Recorded Plat

5. Private Claims

I, RODNEY CLAYPOOL, in a field survey on JUNE 21, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
- M-1 Corner common to four Townships T14 & 15N-R2E and T14 & 15N-R3E

Survey by Government (H. Parke), 1831, set post Survey by F. Gibbs, 1924 Survey by Hunter, 1962 H-W witness card, 1972 Survey by J. Jones, 1981 LCRC by C. McVean, 1994, (Bay Co. Remon Cor) AYPOOL AND VEYOR 29241

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Corner common to four Townships T14 & 15N-R2E and T14 & 15N-R3E

Verified from witness card of 1972 (H-W Eng.)

Found iron and brass cap in mon box (Bay Co. Remon Cor.), per surveys by M. Hunter, J. Jones, and LCRC by C. McVean.

Corner M-/was approved for remonumentation at a Peer Review Committee Meeting on 4/18/96.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-1 Corner common to four Townships T14 & 15N-R2E and T14 & 15N-R3E

Found iron and brass cap in mon box (Bay Co. Remon Cor.), per surveys by M. Hunter, J. Jones, and LCRC by C. McVean; and is accepted as the beavailable evidence of the position of the accepted comer.

S 45 Deg W, 42.07', nail and Bay Co. disc in power pole N 45 Deg W, 89.42', nail and Bay Co. disc in power pole N 40 Deg E, 79.80', nail and Bay Co. disc in power pole \$ 30 Deg E, 137.85',nail and Bay Co. disc in power pole

Signed by Modries D. Claypool

05-10-96

Surveyor's Michigan License No. 29241

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971

Revised Jan., 1983