

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Midland

(County)

Located In

Corner Code #

1. Public Land Survey T T R
2. Property Controlling in Section S 5 T 14N R 1W 4
S 5 T 14N R 1W 8
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Craig W. McVean, in a field survey on Oct. 24, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

4 - None



8 - 2007 - Rec. Sur. L. 7, p. 149 - R. D. Claypool - Set 3/4" pipe. South 8.6' to Fd. rod and cap 19790

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4 - NW 1/16 Corner Sec. 5 - Set 2" Alum. Cap on 5/8" x 34" rebar per Standard BLM procedure. E-W Fence is 5' South. Centerline of N-S drain is 26'± East. East edge of field is 13' East. North 81'± of S. Bank of Drain.

8 - CW 1/16 Corner Sec. 5 - Fd. 3/4" I.D. iron pipe with cap #29241 per Claypool. Also found 1/2" CIR #19790 (R. L. Merry) is S11°48'W 8.54'. Claypool's pipe fits calculated position closely and is accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4 - Stamped 2" Alum. Cap on 5/8" x 34" rebar. Set Blue Carsonite Post with loc. tag 1' SE.
S39°E 46.95' to set N & T in SW side 14" R. Maple
S47°W 6.46' to set N & T in NW side RR tie fencepost
N89°E 22.26' to set N & T in N. side 4" Oak
S5°W 138.09' to set N & T in W. side 26" W. Oak

8 - 3/4" iron pipe with cap #29241.
Set Blue Carsonite Post with loc. tag 1' NE
SE 0.4' to fd. steel fence post
N30°E 42.35' to set N & T in NW side 4" Oak
N57°E 18.11' to set N & T in SE side 11" Oak
S39°E 5.98' to set N & T in NE side 10" R. Maple
N45°W 27.59' to set N & T in SW side 6" R. Maple
S11°48'W 8.54' to fd. 1/2" CIR #19790

Signed by:

Craig W. McVean

Date:

12/10/2012

Surveyor's Michigan License No.:

39088