

# SURVEY & REMONUMENTATION

FEB 23 2001

## SECTION

APPROVED LAND CORNER

P.A. 345 OF 1990  
MIDLAND COUNTY

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Midland County Remonumentation

481

8/24/00 *RR*  
For Corners in  
Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 14N R. 1W

E-11

T. R.

T. R.

2. Public Controlling  
in Section

S. T. R.

S. T. R.

3. Miscellaneous

S. T. R.

Property in Section

S. T. R.

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 14, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1852, Burt

80.36 Cor Sec 28-29-32-33

Aspen 8" S26°E, 17 LINKS

W. Pine 24" N6°W, 57 LINKS

1915, Gibbs

Gas Pipe. Old Corner

Meas. West 40.13'

Meas. North 40.04'

1972, Whittier, LCRC #195

Fd 3/4" pipe 0.6 below B.T. Rd

N50°E, N & D in U.P. 48.38'

N15°W, N & D in P.P. 63.67'

SW to NE Cor Hse #2015, 112.20

1978, Schafer, (132) 2-593

Same as LCRC #195

1978, Schafer, LCRC #448 & (132) 2-545

Fd 1/2" pipe (Meas. West 2641.89)

N50°E, 48.30' Tag in P.P.

N25°W, 63.58' Nail in P.P.

S45°E, 52.92' Nail in T.P. Stub

1980, Campbell, LCRC #522

Fd 1/2" Pipe

Same witnesses as LCRC #448

1986, Jones, (132) 3-918

References Corner in Survey

No Witnesses. Meas. South 2656.08

1996, McGinnis, (132) 5-462

Fd 3/4" pipe (Meas. South 2656.02)

NE 48.15' N & T in U.P.

NW 63.62' N & T in U.P.

SE 52.72' N & T in Post

SW 112.07' Cor of Hse.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 5/8" bar in 3/4" x 18" pinch pipe in Mon Box. Found all recorded witnesses. Meas. East 2650.16 to F-11, West 2641.84 to D-11, and South 2655.98 to E-12. Accepted as best available evidence of the perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe with brass cap stamped "Midland County Remon Corner, P.S. #27458".

Witnesses:

N59°E, 48.16' - N & T in P.P. (OBT)

S43°E, 52.62' - N & T in T.P. Stub (OBT)

S46°W, 112.02' - N.E Cor Hse #2015 (OBT)

N15°W, 63.62' - N & T in P.P. (OBT)

Signed by *Mark R. Robison*

Date *9-15-2000*

Surveyor's Michigan License No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 14, 1997

